




Accident Reference & Bus No: **AR-2022-0405 - SBS5120E with SLP9228A**

Activated date: Mon 30/5/2022 15:02

Activated by: Ang Chong Boon <angcb@sbstransit.com.sg>

Name of Surveyor: Taufik

Company Name: LKK

Date Surveyed: 31May2022

Estimate (before GST) for

Stock Code	Description	Quantity	Total Material cost (S\$)
30122034	WHEELARCH TRIM;N/S&O/S	1	cut ✓ \$41.00
30122013	SIDE PANEL JR~KR.O/S.SIDE PANEL ASSY	1	bt ✓ \$244.00
30122044	SIDE PANEL.O/S&N/S.ALUM	1	bt ✓ \$79.00
90082460	STKR SBS TRANSIT OS/NS.SG BUS	1	rec ✓ \$8.00
30122063	SIDE PANEL GR~HR.O/S.2.5MM ALUM	1	bt ✓ \$95.00
30122040	SIDE PANEL ER~GR.O/S.2.5MM.A/B/C SER8ES	1	bt ✓ \$385.00
30122030	FLAP DOOR FL~GL+FR~GR;0.25X0.3M	1	bt ✓ \$79.00
TOTAL FOR PARTS			S\$ 931.00

- ☐ Parts cost: **\$ 931.00** ✓
☐ Contractor Labour cost: **\$ 850.00** ✓
☐ Workshop Labour cost: **\$ 188.00** ✓
☐ Advertisement Cost: **\$ 0.00** X un
☐ Repair period: **2 days**

Taufik 17495749
 WP 31/5/2022 240pm
 Resurvey before paint
 Taufik e lkkauto.com
 2 days

- ☐ Tow Cost: **\$ 0** X un
☐ Loss of use: **Not required by surveyor** X un
☐ Overheads: **Not required by surveyor** X un

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: