

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22005187/KTY3N2**Date:** 10/06/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30002108179

Claimant Vehicle No : SNE713J**Insured Vehicle No :** YQ2277U

Date of Loss: 27/05/2022

Nature of Claim: TP

Claim No: 275497

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNE713J**

Make & Model: HONDA FREED, 1.5 (A)

Engine No: L15A73840038

Reg. Date: 12/11/2009 (Man. Year: 2009)

Chassis No: MHRGB3860AJ090003

Colour: Metallic Pearl White

Odometer: 212871 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55ZR16

Rear Tyre Size: 205/55ZR16

Front Left Side: Maxxis 8 mm

Rear Left Side: Maxxis 8 mm

Front Right Side: Maxxis 8 mm

Rear Right Side: Maxxis 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,261.44	2,321.68	939.76	28.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,210.00	645.00	565.00	46.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,471.44	2,966.68	1,504.76	33.65
Approved Total (Overridden) (S\$)		2,350.00		
Nett Amount (S\$)	4,471.44	2,350.00	2,121.44	47.44

INSPECTION

Date of Assignment: 31/05/2022

Date Inspected: 01/06/2022 Inspected At:

E M Solution Pte Ltd (HQ)
160 Sin Ming Drive,, #03-18, Sin Ming Autocity
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2022)
Parts:	M1-MPV	HONDA FREED 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNE713J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,464.30 FL	*1,288.00 FL
2	1		*REAR TAILGATE HONDA LOGO	Necessary	28.40 FL	*28.40 FL
3	1		*REAR TAILGATE FREED EMBLEM	Necessary	44.40 FL	*44.40 FL
4	1		*REAR WINDSCREEN	Shattered	1,683.40 FL	*1,260.00 FL
5	1		*THIRD BRAKE LIGHT	Cut	231.30 FL	*231.30 FL
6	1		*WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
7	1		*SET REAR IN-CAR	Serviceable	450.00 FS	*- FS
					Sub Total (\$\$)	3,951.80
					- List Item Discount on L Items 20.00/20.00% (\$\$)	690.36
					Total Parts (\$\$)	3,261.44
						2,892.10
						570.42
						2,321.68

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS,CHECK LIGHTINGS	New	50.00	15.00
2	TO REMOVE,REINSTAL REAR WINDSCREEN	New	180.00	120.00
3	TO REMOVE,TRANSFER TAILGATE COMPONENTS	New	100.00	60.00
4	TO REMOVE,REPAIR & REPLACE DAMAGED BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT	New	400.00	200.00
5	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	400.00	220.00
6	RUST PROOFING ON AFFECTED PORTIONS	New	80.00	30.00
Gross Labour Cost (S\$)			1,210.00	645.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >