

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 07 Jun 2022

Preliminary Advice

Insured Vehicle No	: YQ2277U		
TP Vehicle No	: SNE713J	Accident Date	: 27/05/2022
Make	: HONDA FREED	Assignment Date	: 31/05/2022
Date of Inspection	: 01/06/2022	Est. Duration of Repair	: 3
Inspection At	: E M SOLUTION PTE LTD (HQ) 160 SIN MING DRIVE,, #03-18, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,471.44
Revised Amount	:S\$	2,966.68
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,966.68
Lump Sum Repair	:S\$	2,300.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	19,000.00
COE / PARF Rebate	:S\$	6,822.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,178.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (x) Lump Sum repair

- (x) The above survey was conducted on a 'without prejudice' basis.