

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMA 6783A Yr Regn: 18/6/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1797

Colour: Black A/C: Insured / Std / Nil / NA

Sp. Reading: 328640 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JTDZS36410J028074

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. 29/5/22 D.O.I. 1/6/22

Survey held at Borneo

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-9618

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1) _____

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.E. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd		
			Document No. 0		6 Battery Road #38-04 Singapore 049909		
			Document Date 31/05/2022		Work: 65703925		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	18/06/2018	SMA6783A	0	15348	66TP/SMA6783A/300522
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZS3EU10J028074		2ZR0B83934	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SMF4445M ACC DATE:29/05/22 TOW IN:29/05/22 @21:30 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50	100.00
2	B	BP-LAB2 CHECK WIRING AND REFOCUS HEADLAMP				X	180.00
3	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL FRT PORTION				720	1440.00
4	B	BP-RES2 RESRPAY ACC AFF AREA FRT PORTION				590	1180.00
5	L	BP-LPO SUPPLY REGN PLATE (PO#) FRT					80.00
6	B	BP-LAB2 CONDUCT LEAK TEST REAR PORTION					180.00
7	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SESNOR					180.00
8	B	BP-LAB2 TRANSFER BOOT LID MECHANISM AND REVERSE CAMERA					540.00
9	B	BP-LAB2 REPL REAR WINDSCREEN				462	466.20
10	Z	BP-BKT SUPPLY PHV STICKER					20.00
11	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SESNOR					180.00
12	B	BP-LAB2 R/I INTERIOR UPHOLSTERY TO FAC REPAIR (photo)				360	616.00
13	Z	BP-SLANT SUPPLY SEALANT (NETT)3 PANEL				160	240.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd		
			Document No.		6 Battery Road		
			0		#38-04		
			Document Date		Singapore 049909		
			31/05/2022		Work: 65703925		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	18/06/2018	SMA6783A	0	15348	66TP/SMA6783A/300522
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZS3EU10J028074		2ZR0B83934	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
14	B	BP-LAB2 ^{Replace} RESRPAY ACC AFF PARTS AND PANEL REAR POR 720 x 4				2880	5760.00
15	B	BP-RES2 RESRPAY ACC AFF AREA REAR PORTION 591 x 4				2860	3540.00
16	S	BP-SUBLET RESET ECU UPON COMPLETION OF REPAIR					180.00
17	S	BP-SUBLET REPLACE REAR EXHAUST ASSY					360.00
18	1	U53102-47180 GRILLE SUB-ASSY, / BR	1.00	597.00			597.00
19	2	U52128-47040 COVER, FR BUMPER / MC	1.00	25.80			25.80
20	3	U52543-47030 SEAL, FR BUMPER / MC	1.00	28.60			28.60
21	4	U52611-47100 ABSORBER, FR BUMPER / ?	1.00	84.20			84.20
22	5	U53395-47030 SEAL, HOOD TO FR END / BR	1.00	108.50			108.50
23	6	U52119-47969 COVER, FR BUMPER / ?	1.00	589.50			589.50
24	7	U53111-47110 GRILLE, RADIATOR / ?	1.00	510.10			510.10
25	8	U81070-47660 UNIT ASSY, HEADLAMP, X	1.00	2678.10			2678.10
26	9	U81140-47660 UNIT ASSY, HEADLAMP, X	1.00	2678.10			2678.10
27	0	U75310-33050 EMBLEM ASSY, X	1.00	112.30			112.30
28	1	U75441-47130 PLATE, LUGGAGE COMPT / MC	1.00	58.00			58.00
29	2	U75442-47080 PLATE, BACK DOOR / MC	1.00	67.20			67.20
30	3	U52016-47060 ARM SUB-ASSY, RR / ?	1.00	186.30			186.30
31	4	U52015-47080 ARM SUB-ASSY, RR / ?	1.00	186.30			186.30
32	5	U52023-12240 REINFORCEMENT / ?	1.00	230.20			230.20
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd							
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		
					Lubrication/Fluid		
					Others		
							Amount Due

Customer Copy

Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no : 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No.				
			0				
			Document Date				
			31/05/2022				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	18/06/2018	SMA6783A	0	15348	66TP/SMA6783A/300522

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZS3EU10J028074	2ZR0B83934	60	Shashitharan	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
33	6	U52159-47912 COVER, RR BUMPER <i>BR</i>	1.00	589.50		589.50
34	7	U52156-47010 SUPPORT, RR BUMPER <i>BR</i>	1.00	151.20		151.20
35	8	U52155-47010 SUPPORT, RR BUMPER	1.00	151.20		151.20
36	9	U52576-47030 RETAINER, RR BUMPER <i>OR</i>	1.00	62.70		62.70
37	0	U52575-47030 RETAINER, RR BUMPER	1.00	62.70		62.70
38	1	S52161-0K040 PIECE, RR BUMPER <i>OR</i>	1.00	4.30		4.30
39	2	U76891-47040 SPOILER, RR NO.1 <i>OR</i>	1.00	899.70		899.70
40	3	U58307-47080 PANEL SUB-ASSY, BODY <i>OR</i>	1.00	738.00		738.00
41	4	U58311-47091 PAN, RR FLOOR <i>X</i>	1.00	739.90		739.90
42	5	U67935-47010 C0 PLATE, BACK DOOR	1.00	192.50		192.50
43	6	U58410-47011 C0 BOARD ASSY, DECK <i>X</i>	1.00	575.40		575.40
44	7	U68105-47190 GLASS SUB-ASSY, BACK <i>OR</i>	1.00	1093.60		1093.60
45	8	U56117-50140 DAM, WINDOW GLASS <i>OR</i>	1.00	30.60		30.60
46	9	U67881-47040 WEATHERSTRIP, BACK <i>X</i>	1.00	355.10		355.10
47	0	U67005-47460 PANEL SUB-ASSY, BACK <i>OR (Tailgate)</i>	1.00	1177.30		1177.30
48	1	U67750-47050 C0 BOARD ASSY, BACK	1.00	348.70		348.70
49	2	U69350-28151 LOCK ASSY, BACK DOOR	1.00	437.70		437.70
50	3	U81551-47262 LENS & BODY, RR <i>X</i>	1.00	730.90		730.90
51	4	U81561-47252 LENS & BODY, RR <i>X</i>	1.00	706.10		706.10
52	5	U17430-37480 PIPE ASSY, EXHAUST <i>X</i>	1.00	798.70		798.70

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle 	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 31/05/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW Q2	18/06/2018	SMA6783A	0	15348	66TP/SMA6783A/300522
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZS3EU10J028074		2ZR0B83934	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
53	6	U17565-22040 SUPPORT, EXHAUST	2.00	52.20		104.40	
54	7	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	2.00	108.00		216.00	
55	8	T21000-22 SIKI 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00	
56	9	TREVSE-47006 221 BACK SENSOR BLACK AGEHA	1.00	101.05		101.05	
<i>Stev (LKK)</i> <i>17/6/22, 12:30h</i> <i>W R</i> <i>11 dy</i> <i>p/p</i> <i>by Rn Y</i>							
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis							
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 33,849.65
Acknowledged by Repairer Signature: Date:			Please acknowledge receipt of vehicle		Parts 18,607.45 Labour 14,622.20 Sublet 620.00 Lubrication/Fluid 0.00 Others 0.00		GST 7.00% 2,369.48 Less 0.00 Amount Due 36,219.13

Customer Copy