

Not Authorised
Returning B9p9m
Ex @500k
5day

VEHICLE NO: SGT7769G

MODEL: MERCS E200

CHASSIS NO: W1K2130042A876588

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>	
FRONT BUMPER	CM \$ 1,100.00 ✓
FRONT BUMPER RETAINER RHS	\$ 100.00 ✓
FRONT BUMPER TOWING COVER	\$ 80.00 ✓
FOG LAMP COVER RHS	\$ 100.00 ✓
FRONT BUMPER CHROME GARNISH RHS	\$ 150.00 ✓
HEADLAMP RHS	Bu \$ 4,000.00 ✓
FRONT FENDER RHS	Bu \$ 1,600.00 ✓
FRONT FENDER INNER SHIELD RHS	CM \$ 430.00 ✓
FRONT BONNET <i>(Aluminium)</i>	Bu \$ 2,600.00 ✓
FRONT LOWER ARM RHS	Bu \$ 600.00 X
FRONT STEERING KNUCKLE RHS	Bu \$ 2,100.00 X
FRONT ABSORBER RHS	Bu \$ 890.00 X
FRONT WHEELHUB W/BEARING RHS	\$ Bu 630.00 X
FRONT REINFORCEMENT	\$ 2,400.00 7
WIPER RESERVOIR	\$ 200.00 7
FRONT SENSORS RHS	mil \$ 270.00 ✓
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____	
<u>SPECIAL NETT ITEMS</u>	
FRONT BUMPER CLIPS 1 SET	\$ Bu 60.00 ✓
FRONT CARPLATE	\$ Bu 60.00 X
Total	\$ 120.00
TOTAL PARTS	\$ 15,645.00

10%
 \$ 17,250.00
 \$ 1,725.00
\$ 15,525.00

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,800.00	5001
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,800.00	7501
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	201
4	To provide anti-rust treatment on affected areas	\$ ~2 100.00	X
5	Dignostic Check	\$ 100.00	7
6	Alignment Check	\$ ~ 100.00	X
	Labour Total :	\$ 4,000.00	
	TOTAL (PARTS & LABOUR):	\$ 19,645.00	