

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CCG/A1622005214/Ueq3**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ )

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$ )

Interview (\$ )

Tech. Invs (\$ )

Weekend (\$ )

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

7/6/22 2/5 @ 8000 informed Allen.

FASTECH AUTO PTE LTD  
1 Kaki Bukit Ave 6 #01-48 Autobay  
Singapore 417883  
Tel No: 67452063/ 67467158 Fax No: 67458520  
Tax Reg No : 200006262D

Asher

not Authorized  
1/6/22  
1/5# 8000/  
5-days

VEHICLE No: SME1201A

1PC	REAR WINDSCREEN MOULDING	new		\$166.20	
1PC	TAILGATE	Body ID	1254.20	\$1,455.20	
1PC	TAILGATE REAR LOGO	11		\$48.00	X
2PCS	TAILGATE REFLECTORS @\$341.60	11		\$683.20	X
1PC	TAILGATE 'SHUTTLE' EMBLEM	new	72.00	\$75.00	
1PC	TAILGATE OUTER GARNISH	11		\$495.00	X
1PC	TAILGATE INNER LOCK	3mf	265.10	\$288.20	
1PC	TAILGATE INNER TRIM BOARD	De/cne	415.20	\$455.10	
1PC	TAILGATE WEATHERSTRIP	twi		\$232.80	
2PCS	TAILLAMPS @\$950.00	cne	685 x 2 = 1370	\$1,900.00	
1PC	REAR BUMPER	DIS	985	\$1,415.10	
2PCS	REAR BUMPER SIDE RETAINERS @\$45.00	3mf		\$90.00	
2PCS	REAR BUMPER REFLECTORS @\$75.00	11		\$150.00	X
2PCS	REAR BUMPER SIDE COVERS @\$111.00	11		\$222.00	X
1PC	REAR BUMPER INNER SPONGE	NZ		\$183.00	X
1PC	REAR END PANEL	Body ID	691.00	\$755.20	
1PC	REAR END PANEL TOP GARNISH	twi		\$248.70	
1PC	REAR END PANEL ANTENNA SENSOR	cne		\$108.90	
2PCS	REAR END PANEL SIDE EXTENSION PANELS @\$285.00	3mf/ID		\$570.00	
1PC	REAR EXHAUST	11		\$688.20	X
1PC	REAR FLOOR PANEL TOP BOARD	SW		\$544.10	X
1PC	REAR FLOOR PANEL	R		\$1,140.20	X
1PC	REAR FLOOR PANEL TOOLS TRAY	cne	495.20	\$652.30	
1PC	REAR BUMPER TOOLS SPONGE	Torn	588	\$588.00	
2PCS	REAR FENDER INNER TRIM BOARDS @\$690.00	De/Torn	485 x 2 = 970	\$1,380.00	
1PC	REAR FENDER	R		\$1,155.20	X
				\$15,689.60	

(20%)

S.NETT

1PC	REAR WINDSCREEN SEALANT	new		\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	new		\$50.00	40
1SET	REAR BUMPER REVERSE SENSOR	short		\$280.00	200
1SET	TAILGATE INNER TRIM BOARD CLIPS	new		\$50.00	
1SET	REAR BUMPER CLIPS	new		\$60.00	50
1PC	REAR BUMPER TOP CHROME PLATE	3mf		\$380.00	280
1PC	REAR END PANEL SEALANT	new		\$50.00	
1SET	REAR FLOOR PANEL INSULATOR	NF		\$200.00	X

TO CHECK WIRING

\$50.00 20

TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO SPRAY RUST PROOFING	\$100.00	80
TO RESET DIAGNOSTIC & REPROGRAMME SYSTEM	\$120.00	50
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,800.00	1000
TO PUTTY & SPRAY PAINTING	\$1,800.00	1100
<b>TOTAL</b>	<b>\$21,129.60</b>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

P- 8522.3  
202  
6817.84  
710  
2540  
10667.84