

ASS. REC. BY:

REF: TM1Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$27,390

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 08 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 Get B2Call by \$6000 maxVeh No: SHD 2876Yr Regn: 11.15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: RenaultC.C. 1995Colour: M. White / Red

A/C: Insured / Std / NI / NA

Sp. Reading: 83819

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: V121 ABL 15 AUG 28 2311Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 7 mm

Rear

R/Bal. 8 mmL/Bal. 7 mmL/Bal. 8 mmD.O.A. 31/5/22D.O.I. 1/6/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

F. + TS

Others

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
 SHD267G

AAD2205-144

Not Authored
61 Emp \$6000. Max

Vehicle No.:
 UEN No:
 Vehicle Make: **01 JUN 2022**
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD267G
200303878K
RENAULT
LATITUDE
31.5.2022
SLC1804H / TOKIO MARINE
20/11/2015

PART		LIST
1 BUMPER COVER REAR	\$	<i>B₁</i> 561.70 ✓
1 BUMPER LOWER REAR	\$	<i>D₁</i> 411.90 ✓
1 BUMPER BRACKET CTR REAR	\$	<i>D₁</i> 98.10 ✓
1 BUMPER BRACKET SIDE RH REAR	\$	<i>S₁</i> 82.10 X
1 BUMPER RETAINER RH REAR	\$	<i>S₁</i> 59.80 X
1 BUMPER BRACKET SIDE LH REAR	\$	<i>D₁</i> 80.80 ✓
1 BUMPER RETAINER LH REAR	\$	<i>D₁</i> 54.20 ✓
1 ABSORBER REAR	\$	<i>N/A</i> 217.30 X
1 BUMPER BEAM REAR	\$	<i>B₁</i> 547.80 ✓
1 BUMPER BEAM BRACKET LH REAR	\$	<i>B₁</i> 114.50 ✓
1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 114.50 X
1 OUTER PANEL REAR (End Panel)	\$	<i>B₁</i> 745.80 ✓
1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>CM</i> 404.56 ✓
1 SPARE WHEEL PANEL	\$	<i>R</i> 1,229.40 X
1 SPARE TYRE BOARD	\$	<i>S₁</i> 680.90 X
1 TAILLAMP LH	\$	<i>CM</i> 401.40 ✓
1 TAILLAMP RH	\$	<i>S₁</i> 401.40 X
1 BOOT REAR	\$	<i>B₁</i> 1,677.20 ✓
1 BOOT BADGE 'RENAULT'	\$	<i>R₁</i> 82.40 ✓
1 BOOT BADGE	\$	<i>R₁</i> 95.80 ✓
1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 277.70 ✓
1 BOOT REFLECTOR LAMP RH	\$	<i>S₁</i> 277.70 X
1 BUMPER REFLECTOR LH	\$	<i>B₁</i> 16.60 ✓
1 BUMPER REFLECTOR RH	\$	<i>S₁</i> 16.60 X
1 BOOT HINGE LH	\$	<i>R</i> 254.20 X
1 BOOT HINGE RH	\$	<i>R</i> 254.20 X
1 BOOT STRUT LH	\$	<i>S₁</i> 145.10 X

Trans-cab Auto Services Pte Ltd

AAD2205-144

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD267G

1 BOOT STRUT RH	\$	1m 145.10 X
1 BOOT LOCK	\$	1m 246.60 X
1 BOOT LOCK CATCH	\$	1m 41.70 X
1 BOOT FINISHER	\$	1m 344.70 X
1 FENDER PANEL REAR LH	\$	1m 1,933.20 ✓
1 WHEELARCH REAR LH	\$	1m 275.40 X

\$	12,290.36
10% \$	1,229.04
\$	<u>11,061.32</u>

Special Nett

1SET PARKING AID	\$	Phon 700.00 400m
1SET REAR BUMPER CLIP	\$	na 66.00 ✓
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00 X
1SET BUMPER RETAINER RH CLIP RR	\$	na 20.00 X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na 10.00 X
1SET BUMPER RETAINER CLIP LH RR	\$	na 20.00 X
1SET BUMPER LOWER REAR CLIP	\$	na 66.00 ✓
1 EXHAUST MOUNTING REAR	\$	1m 17.82 X
1 REAR BOOT STICKER 'Trans-cab'	\$	1m 80.00 30m
1 REAR BOOT STICKER '6555-3333'	\$	1m 80.00 30m
2 WINDSCREEN SEALANT	\$	1m 150.00 40m
1 WINDSCREEN MOULDING	\$	na 200.00 X
1 WINDSCREEN INNER SPONGE SEAL	\$	na 130.00 30m

TOTAL	\$	1,549.82
TOTAL PARTS	\$	<u>12,611.14</u>

LABOUR

Putty And Spray Painting Of The Affected Portion. \$ 2,000.00 8801

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same \$ 2,000.00 12001

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD267G

AAD2205-144

To Rust-Proofing Of The Affected Areas.	\$	170.00	901
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	nn X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	nn X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	1001
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	129
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To Check Electrical Lighting Concerned.	\$	170.00	201
TOTAL	\$	5,580.00	

Over All Total \$ 29,252.47

(LUMP SUM)

Repair Days

14 DAYS
8 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHD267G
Vehicle to be Exported:	No
Intended Deregistration Date:	31 May 2022
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002921
Chassis No.:	VF1ABL15AUC282311
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	20 Nov 2015
First Registration Date:	20 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Nov 2023
PARF Rebate Amount:	\$12,998.00

Intended COE Rebate Details

COE Expiry Date:	19 Nov 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,267.00
COE Rebate Amount:	\$8,314.00
Total Rebate Amount:	\$21,312.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 31 May 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	31/05/2022 13:43 (SGT)
Date of Accident	31/05/2022 08:35 (SGT)
Exact Location of Accident	Near 20 Malcolm Rd, Singapore 308259
Additional Location Information	PIE TOWARDS TUAS BEFORE STEVENS ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD267G
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Company Reg No	2XXXXX878K
Email Address	claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62876666
Alternative Phone No	(Office) +65-62876666

VEHICLE PARTICULARS

Manufacturer	Renault
Model	Latitude
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1998

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	VFX/P2413997
Cover Note Number	NA

DRIVER

Name of Driver	WONG KHENG SIONG
NRIC No	SXXXX779D

Date Of Birth	21/09/1968
Occupation	Outdoor
Date Of Driving Pass	15/08/1996
Driving experience	25 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96901685
Alt. Phone Number	-
Email Address	claims@transcab.com.sg
Address	984A BUANGKOK LINK
Address complement	#16-11
Postcode	531984
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	P1
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Tampines Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18005871999
Alt. Police Station Phone No	(Fax) +65-65871699
Police Station Address	6 Tampines Ave 4 Singapore 529682
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT


REFER TO POLICE REPORT

ATTACHMENT(S)


Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	WITH TRANSCAB.
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC1804H
-----------------------------	----------



30042021



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
WONG JUN KEAT

Reporting Centre Personnel's Signature
Name:
ARC/RN No.:



SINGAPORE POLICE FORCE



T/20220531/2022

1 of 3

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20220531/2022

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/05/2022 11:46		Vide Report No.:		Station Diary No.: 31	
Informant's Particulars					
Name of Informant: WONG KHENG SIONG			Address: APT BLK 984A BUANGKOK LINK #16-11 SINGAPORE 531984		
ID Type / ID No.: NRIC NO / S6836779D			Contact No.: Home/Office: Mobile: 96901685		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 53	Date of Birth: 21/09/1968	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 31/05/2022 08:35	Type of Location: Express Way
Location: PAN-ISLAND EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 80 Km/h	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD267G	Car	RENAULT	LATITUDE 2.0L DCI AUTO	Red	Slightly Damaged	1
SLC1804H	Car	HONDA	JAZZ 1.5 VTIR	Silver	Slightly Damaged	0
SLG2032R	Car	TOYOTA	COROLLA AXIO 1.5X	Beige	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20220531/2022

2 of 3

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No. T/20220531/2022

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	WONG KHENG SIONG	ID No.	S6836779D
Related Vehicle	SHD267G (Car)	Contact No.	96901685
Hospital/Clinic	SUNSHINE CLINIC FAMILY PRACTICE & SURGERY	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	31/05/2022	Date Discharge	31/05/2022
No. of Days granted Medical Leave	07	Degree of Injury	Slight

Brief Details.

On the abovementioned date and time, I was driving on the first lane along PIE towards Tuas before Stevens Rd exit.

The vehicle in front of me slowed down, I also slowed down however the vehicle behind me, SLC1804H did not manage to brake in time and hit my car from the rear. There was also another hit from SLG2032R, the vehicle behind SLC1804H, thus forming a 3 vehicle pile up along lane 1. Subsequently, I left the scene and headed to the clinic. I suffered pains on my neck, back, and legs. I was given 7 days MC.

I would like to state that my vehicle is equipped with front and rear cameras.