



TeamWork Garage Pte Ltd  
 53 Ubi Avenue 1 #01-23/24 Spore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475  
 E-mail : claims@teamworkgarage.com  
 ROC number : 201015366H  
 OWN DAMAGE CLAIM

ALLIANZ

|                |                      |
|----------------|----------------------|
| Vehicle number | SNB2005Y             |
| Make / Model   | LAMBORGHINI AVENTADO |
| Chassis number | ZHWEC1476CLA00558    |
| Accident date  | 19/5/22              |
| Reference      | 2205-31              |

| Qty                                   | Particulars                                   | Unit Price - SGD \$           |
|---------------------------------------|-----------------------------------------------|-------------------------------|
| <u>PARTS REPLACEMENT - LIST ITEMS</u> |                                               |                               |
| 1                                     | FRONT BUMPER WITH SENSOR HOLE                 | 20000.00 /DT                  |
| 4                                     | FRONT BUMPER PDC SENSOR                       | 1520.00 /cut                  |
| 4                                     | FRONT BUMPER SENSOR BRACKET                   | 340.00 /BT                    |
| 2                                     | FRONT BUMPER RETAINER                         | 360.00 /nec                   |
| 1                                     | FRONT BUMPER TRIM (COVER) RH                  | 1500.00 /cut                  |
| 1                                     | FRONT BUMPER SPOILER                          | 7000.00 /cut                  |
| 1                                     | FRONT BUMPER DAMPING ELEMENT (FOAM)           | 1800.00 /cut                  |
| 1                                     | FRONT BUMPER REINFORCEMENT                    | 2800.00 /DT                   |
| 1                                     | FRONT BUMPER MIDDLE LOWER GRILLE              | 800.00 /cut                   |
| 1                                     | FRONT BUMPER SIDE GRILLE RH                   | 400.00 /cut                   |
| 1                                     | FRONT BUMPER LAMBORGHINI EMBLEM               | 750.00 /nec                   |
| 1                                     | FRONT BUMPER UNDER BODY TRIM                  | 2800.00 /cut                  |
| 1                                     | FRONT BUMPER UNDER BODY TRIM RH               | 2800.00 /cut                  |
| 1                                     | FRONT GRILLE BRACKET HOLDER                   | 1800.00 /DT                   |
| 1                                     | BONNET                                        | 16525.00 /DT                  |
| 1                                     | BONNET UPPER CATCH HOOK                       | 150.00 X Svc                  |
| 1                                     | BONNET LOWER LOCK                             | 50.00 X Svc                   |
| 1                                     | BONNET RELEASE CABLE                          | 220.00 X Svc                  |
| 2                                     | BONNET ABSORBER                               | 220.00 /DT                    |
| 2                                     | FRONT HEADLAMP                                | 16840.00 /Cr                  |
| 1                                     | FRONT HEADLAMP CONTROL MODULE RH              | 850.00 X Svc                  |
| 2                                     | FRONT HEADLAMP BRACKET                        | 60.00 /DT                     |
| 2                                     | FRONT HEADLAMP SIDE COVER                     | 1160.00 /cut                  |
| 1                                     | FRONT HEADLAMP CONTROL UNIT FOR GAS DISCHARGE | 880.00 <del>880.00</del> /nec |
| 1                                     | HEADLAMP POWER MODULE FOR DAY DRIVING LIGHTS  | 675.00 <del>675.00</del> /nec |
| 1                                     | HEADLAMP INJECTOR UNIT FOR HEADLAMP CLEANING  | 260.00 <del>260.00</del> /nec |
| 1                                     | HEADLAMP SIDE MARKET SIGNAL LIGHTS            | 495.00 /nec                   |
| 1                                     | HEADLAMP BLUB                                 | 1080.00 /nec                  |
| 1                                     | LUGGAGE COMPARTMENT TRIM                      | 2224.00 /cut                  |
| 1                                     | LUGGAGE COMPARTMENT LOCK COVER                | 103.00 /cut                   |
| 1                                     | LUGGAGE COMPARTMENT SEAL                      | 200.00 /cut                   |
| 1                                     | AIR FILTER BOX                                | 2600.00 /cut                  |
| 1                                     | SIDE COVER RH                                 | 103.00 /cut                   |
| 1                                     | FRONT FENDER RH                               | 4576.00 /DT                   |
| 1                                     | FRONT FENDER BRACKET RH                       | 280.00 /nec                   |
| 1                                     | FRONT FENDER CARRIER RH                       | 60.00 /nec                    |
|                                       |                                               | 94281.00                      |
| Cost +10%                             |                                               | 9428.10                       |
|                                       |                                               | 103709.10                     |

| <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u> |                                           |                           |
|-----------------------------------------------|-------------------------------------------|---------------------------|
| 1 SET                                         | FRONT BUMPER CLIP                         | 300.00 <i>50712</i>       |
| 1 SET                                         | FRONT GRILLE CLIP                         | 300.00 <i>50712</i>       |
| 1                                             | FRONT NUMBER PLATE                        | 150.00 <i>XSV</i>         |
| 1 SET                                         | LUGGAGE COMPARTMENT TRIM CLIP             | 150.00 <i>50712</i>       |
| Subtotal                                      |                                           | 900.00                    |
| <u>LABOUR AND MISCELLANEOUS CHARGES</u>       |                                           |                           |
| 1                                             | TO CHECK WIRING SYSTEM                    | 200.00 <i>50712</i>       |
| 2                                             | TO REPROGRAMM AFTER REPAIR WORKS          | 1000.00 <i>1.800 400</i>  |
| 3                                             | TO R&R FRONT BUMPER ATTACHMENT            | 350.00 <i>70</i>          |
| 4                                             | TO R&R BONNET ATTACHMENT                  | 350.00 <i>70</i>          |
| 5                                             | TO REPROGRAMM FRONT HEADLAMP AFTER REPAIR | 1000.00 <i>1.350</i>      |
| 6                                             | TO MOUNT VEHICLE ON BENCH FOR REPAIR      | 800.00 <i>1. XNW</i>      |
| 7                                             | PANEL BEATING ON AFFECTED AREAS           | 2800.00 <i>600 1.900</i>  |
| 8                                             | SPRAY PAINTING ON AFFECTED AREAS          | 2800.00 <i>800 1.1000</i> |
| Subtotal                                      |                                           | 9300.00                   |
| Grand total                                   |                                           |                           |

Thuvun@Lhhquto.com  
82238769

2/6/22 1730

6days w/p

OD

F: 65 0000

113909.1