(08/11/13)	255	1
ASS REC BY:	REF:	(

REF: CS MSG 22005224 Dny3

ASSI	CN	ME	NT
21001	O1 47		111

From: Date:	Veh No: Sat SLV 7644 M Yr Regn: 5an 1 2018
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toyota Voxy Hybrid cc 1797
at Workshop m/s	Colour Skelc A/C: Insured / Std / NI / NA
of	Sp.Reading 390016 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No: 22ROA31087
Policy No.	C/No: ZWR800288160
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Intorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII / S/Rim / STD A/Rim or
	Tyre Size: F: 195 65 R15
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Dunles
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. S mm R/Bal. S mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. S mm L/Bal. S mm
Est. Repairs: days Res.: Yes or No	D.O.A. 25 05 222 D.O.I. 0106 222
Lum Sum: % 3 Val.: Yes or No	Survey held at JWG AMK
CA / REV / REP. / 24 HRS	Des. of Damages : Frt Rear O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT Date: Person Contacted:	· Kn
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
NSter MSIG SLQ 2033K	
13/39/2 man 45 5,506/- win	We do not have a second and a second a second and a second a second and a second a
	Red, 27781.67, 8390)
Date/Time, File Pass to? : Preli. Report Da	ys Of Repair: 5
1) : Final Report Re	survey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fee:	: Site Insp (\$)s+Rs,si
	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ 5500	: Weekend (\$)
	TOTAL

SA0R225Q0001 / Allswell Motor Traders ENTRY DATE & TIME: 26/05/2022 16:28 (SGT) SUBMITTED BY: Ben VERSION: 1 (26/05/2022 16:28 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- A. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission

Date of Accident **Exact Location of Accident**

Additional Location Information

Country/State of Loss

26/05/2022 16:28 (SGT) 25/05/2022 17:25 (SGT)

Singapore

ORCHARD RD TOWARDS PLAZA SINGAPURA INFRONT

ORCHARD GATEWAY

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLV7644M

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No **Email Address**

Mobile Phone No.

Alternative Phone No

ALLSWELL MOTOR TRADERS

5XXXX889J

ben@allswellmotor.com.sg (Phone) +65-98448882

+65-98448882

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category

Transmission

Toyota

Voxy

HYBRID

Private hire

No - Claiming third party

Private hire

Auto

1797

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy Policy Number

Cover Note Number

China Taiping Insurance (Singapore) Pte. Ltd.

Comprehensive

Yes

DMHCSNA00009252101

DRIVER

Name of Driver

OH TEE PING



SXXXX285E NRIC No 16/01/1970 Date Of Birth Outdoor Occupation 26/08/1988 Date Of Driving Pass

33 YEARS AND 9 MONTHS Driving experience

Gender

(Phone) +65-98523057 Mobile Number Alt. Phone Number

Email Address ben@allswellmotor.com.sg

BLK 205 CHOA CHU KANG CENTRAL Address

Male

#09-62 Address complement 680205 Postcode Is the driver the policyholder? No

If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head on collision Weather Conditions Clear

Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes 2

Number of Passengers (Including Driver) Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance? No

PASSENGER 1

PARK MI JONG Name

Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? No Was notice of intended Prosecution given? No

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

ON THE STATE DATE AND TIME, I, VEHICLE A (SLV7644M) WAS TRAVELLING STRAIGHT ALONG AT THE STATED LOCATION ON LANE 3. AS VEHICLES INFRONT OF ME SLOWED DOWN AND CAME TO A STOP, I FOLLOWED SUIT. SECOND LATER, I FELT AN IMPACT FROM MY REAR PORTION, VEHICLE B (SLQ2033K) COLLIDED ONTO THE REAR PORTION OF MY VEHICLES CAUSING DAMAGES.

ATTACHMENT(S)

Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLQ2033K

Vehicle Manufacturer



Page 2 of 15

Describ	e Cir	cum	stance:	s of th	re Acc	cider	nt										
		On	the	state	dat		wid -	time,	1 /	vehicle	A (9EV 79	,44n) W	as fravo	elling s	traight
along	sit	the	stated	(00	Hism	19	lane	3.	As	uehicle	ş M	front	of	ng	dowed	down	and
came	tu	А	stop	, 1	Pollo	wed	JVI.	t. Se	cond	14fer	, \	felt	Я'n	impo	(+ fio	m rey	rear
portion	, ,	ehicl	e B	[21Q	2033/	() حر	Nided	ento	th	e rear	porti	on d	m	y J	ehicles	causi	ing
dama	10/2(***************************************					
	13-																

	-																

***************************************	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,									XIII							
												01151155					

Declaration

(We declare the foregoing particulars are true in every respect.

Tiadera #

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	889J
Vehicle Details	
Vehicle No.:	SLV7644M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 May 2022
Vehicle Make:	TOYOTA
Vehicle Model:	VOXY HYBRID 1.8X CVT
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	2ZR0A31087
Chassis No.:	ZWR800288160
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$30,735.00
Original Registration Date:	15 Jan 2018
First Registration Date:	15 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$25,029.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jan 2028
PARF Rebate Amount:	\$18,771.00
Intended COE Rebate Details	14.1 2020
COE Expiry Date:	14 Jan 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,289.00
COE Rebate Amount:	\$25,517.00
Total Rebate Amount:	\$44,288.00

The information contained herein is correct as at 26 May 2022 $\,$

SGCARMART.COM

Login Sign up f Connect Q

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

0

Insurance

Articles

Forum

Resources











Save this search criteria, to get email alerts whenever a match is found.											
	Make		Model	~)\$	Price V	Depreciation ~	Reg Date V	€ Eng Cap ∨	♣ Mileage ∨	♦ Veh Type ∨	\$ Status ✓ \$
For old advertisem	nents, view Expire	d ads								20	✓ results/page

Buy / Rent Cars	Sell Your Car	Aftermarket	Articles	General
New Cars For Sale	Post an Ad	Workshop Directory	Car Reviews	About Us
Used Cars For Sale	Sell by Bidding	Aftermarket Products	Car Advice	Contact Us
Cars For Rent	Sell by Consignment		Car News	Careers
			Car Features	Site Map

Res Compare &

JWG INTERNATIONAL PTE. LTD

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592 E-Mail: jwg.claims@yahoo.com

Motor Claims Dept

ATG MSIG

To:

Att:

 To resurvey before/after spray painting . To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

· Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

ACCIDENT INVOLVING SLQ2033K [YOUR INSURED] & SLV7644M [OUR CLIENT] ON 25/05/2022.

ESTIMATED REPAIR COSTS FOR SLV7644M

QTY	<u>PARTS</u>	AMOUNT
1PC	TAILGATE Devil 1812.00	\$ 2,406.10
1PC	TAILGATE WINDSCREEN MOULDING べし 135.00	\$ 407.20
1PC	TAILGATE CHROME MOULDING HH	\$ 988.20 >
1PC	TAILGATE TOYOTA LOGO HE HH	\$ 58.80
1PC	TAILGATE 'VOXY' EMBLEM HALL HA	\$ 103.90
2PC	TAILGATE NO. PLATE LAMP L+R @ \$107.68 EACH	\$ 215.36
1PC	TAILGATE INNER TRIM BOARD month work 425.00	\$ 1,093.70 \
1PC	TAILGATE WEATHER STRIP N/c 371.75	\$ 725.50
1PC	TAILGATE LOCK & Dem	\$ 461.50
1PC	TAILGATE HYBRID EMBLEM HE	\$ 62.15
2PC	TAILGATE HINGE LH / RH @ \$104.20 EACH	\$ 208.40
2PC	TAILGATE DAMPER LH / RH @ \$609.10 EACH	\$ 1,218.20
1PC	REAR BUMPER distant Dente 798.20	\$ 1,491.90
2PC	REAR BUMPER SIDE RETAINER L+R @ \$129.92 EACH →	\$ 259.80
2PC	REAR BUMPER BRACKET L+R @ \$158.39 EACH	\$ 316.78
2PC	REAR BUMPER REFLECTOR L+R @ \$145.80 EACH	\$ 291.60
1PC	REAR BUMPER TOW HOOK COVER ⊢	\$ 91.80
1PC	REAR END PANEL INNER 2000 (4) 533.70	\$ 1,205.90
1PC	REAR END PANEL OUTER Den 685.10	\$ 1, 420 .85
1PC	REAR END PANEL TOP GARNISH money dynal 204.50	\$ 383.82
1PC	SPARE WHEEL PANEL HH	\$ 2,876.20
1PC	SPARE WHEEL PANEL TOP BOARD to Sue 164 830.00	\$ 1,409.20
2PC	REAR FENDER LH / RH @ \$2,985.70 EACH	\$ 5,971.40
2PC	REAR FENDER INNER TRIM BOARD L+R @ \$868.48 EACH	\$ 1,736.96
2PC	REAR FENDER QUARTER GLASS MOULDING @ \$499.80 EACH	\$ 999.60
2PC	TAIL LAMP L+R @ 1,389.85 EACH	\$ 2,779.70
2PC	TAIL LAMP LOWER BRACKET L+R @ \$174.25 EACH	\$ 348.50
2PC	TAIL LAMP PANEL L+R @ \$898.00 EACH	\$ 1,796.00
2PC	TAIL LAMP LOWER GARNISH LH / RH @ \$498.75 EACH 0 5 CACH	\$ 99 7.5 0
1PC	REAR EXHAUST PIPE HA	\$ 1,573.90
1PC	REAR EXHAUST HEAT SHIELD	\$ 288.80

1PC	REAR EXHAUST MOUNTING	7	1	\$ 98.00
1PC	REAR EXHAUST DIFFUSER COVE	R H	3	\$ 355.00
		(1)8()	PARTS SUM:	\$ 34,642.22
		6628.60	PARTS LESS 25%:	100
	7	4971.46	PARTS TOTAL:	\$ 25,981.67

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY 1 SET REAR REVERSE SENSOR MG	\$	300.00 🗡
*	TO SUPPLY REAR END PANEL SEALANT	\$	8,0.00 401-
*	TO SUPPLY REAR FENDER SEALANT	\$	80.00 ×
*	TO SUPPLY REAR WINDSCREEN SEALANT	\$	80.00 401-
*	TO SUPPLY REAR WINDSCREEN DAMPING SEAL	\$	30.00 ×
*	TO SUPPLY REAR FLOOR PANEL SEALANT	\$	80.00 ×
*	TO SUPPLY TAIL LAMP PANEL SEALANT by	\$	80.00 ×
*	TO SUPPLY TAIL LAMP CLIPS	\$	50.00 ×
*	TO SUPPLY REAR BUMPER CLIPS >- Lec	\$	50.00 201-
*	TO SUPPLY REAR END PANEL TOP GARNISH CLIPS	\$	50.00 151-
*	TO SUPPLY REAR FENDER INNER TRIM CLIPS	\$	50.00 %
*	TO SUPPLY TAILGATE INNER TRIM BOARD CLIPS No.	\$	50.00 151-
		•	2000 15/-
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	\$	3,00.00 80/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$	2,000.008001
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$	2,000.00 700/-
*	TO TUFF COAT DAMAGED AREAS	\$	300.00 40 -
*	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	\$	300.00 ⊣⊣
*	TO RNR REVERSE CAMERA	\$	100.00 ⊣⊣
*	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	\$	250.00 120/-
*	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$	200.00 60 -
*	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$	250.00 ⊣ы
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$	200.00 ны
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$	300.00 ⊣
*	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	\$	120.00 HH
0 (LABOUR & S/N TOTAL:	\$	7,300.00
	GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST):		
	Honey 5 days.		
	2 (10 10 20 10 20 10 10	1-4	5
	9 ya LKK And Crede 7 ch prices. 1/5 5,	500	