



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0443/2022/JT
DATE	:	30-May-22
WIP	:	26308

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/5/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME	:	MR ONG CHENG HOCK
ADDRESS	:	BLK 556 PASIR RIS ST 81 #11-153 SINGAPORE 510556
TELEPHONE	:	HP +65 9755 5596
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070005647-02
VEHICLE NO	:	SMR 6980 H
MODEL CODE	:	AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR	:	17/1/2020
ENGINE NO	:	CZD 887174
CHASSIS NO	:	WAUZZZF3XL1026457
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	28-May-22
PLACE OF ACCIDENT	:	SLIP ROAD AT PASIR RIS DRIVE 8

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 6980 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 X	
3	TO REMOVE AND RENEW AIRCON CONDENSER. TO REMOVE AND REINSTALL ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 1,700.00 X	
4	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,000.00 800 ✓	
5	TO RESPRAY FRONT BUMPER.	\$ 1,200.00 850 ✓	
6	TO APPLY APPROVAL FOR LTA OPC LETTER.	S/N \$ 280.00 ✓	
SUB-TOTAL LABOUR CHARGES		: \$ 8,060.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 6980 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	Lod
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 8,532.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 6980 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER	1	\$	1,235.00	✓CUT
2	FRONT BUMPER CLOSING ELEMENT - LH	1	\$	66.00	XSLC
3	FRONT BUMPER GRILLE - CENTER	1	\$	242.00	XSLC
4	RADIATOR GRILLE COVER - LOWER	1	\$	58.00	XSLC
5	FRONT BUMPER GRILLE - LH	1	\$	124.00	XSLC
6	FRONT BUMPER CLOSING ELEMENT - LOWER	1	\$	212.00	XSLC
7	FRONT BUMPER SPOILER	1	\$	426.00	XSLC
8	FRONT BUMPER BRACKET	1	\$	24.00	XSLC
9	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$	171.00	XSLC
10	RADIATOR GRILLE COVER - LOWER	1	\$	1,594.00	✓CUT
11	RADIATOR GRILLE STRIKER PLATE	1	\$	271.00	XSLC
12	RADIATOR GRILLE COVER CAP	1	\$	47.00	XSLC
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$	974.00	?
14	FRONT BUMPER FOAM FILLER PIECE	1	\$	114.00	?
15	FRONT BUMPER GUIDE SECTION - LH	1	\$	43.00	?
16	FRONT BUMPER TOP COVER	1	\$	137.00	XSLC
17	AIR COND STICKER	1	\$	9.00	XSLC
18	CAUTION STICKER	1	\$	16.00	XSLC
19	FRONT PARKING AID SENSOR	2		TBC	XSLC
20	FRONT PARKING AID SENSOR SEAL RING	4	\$	10.00	XSLC
SUB TOTAL SPARE PARTS		:	\$	5,773.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 6980 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	HORN - LH	1	\$	153.00	XSV
22	HORN SUPPORT - LH	1	\$	25.00	XSV
23	HEADLIGHT MOUTING - LH	1	\$	132.00	XSV
24	LIFT CYLINDER - LH	1	\$	231.00	XSV
25	LIFT CYLINDER HOSE	1	\$	92.00	XSV / cut
26	LIFT CYLINDER PUMP	1	\$	171.00	XSV
27	WINDSCREEN WAHSEY SYSTEM PUMP	1	\$	137.00	XSV
28	WASH WATER RESERVOIR	1	\$	240.00	XSV
29	WASH WATER RESERVOIR END CAP	1	\$	24.00	XSV
30	HEADLIGHT - LH	1	\$	5,952.00	XSV
31	FRONT WHEEL ARCH COVER - LH / RH	2	\$	566.00	XSV
32	LOCK CARRIER	1	\$	1,412.00	XSV
33	A/C CONDENSER	1	\$	569.00	XSV
34	RADIATOR COOLANT	6	\$	282.00	XSV
35	RADIATOR AIR GUIDE - LH	1	\$	43.00	XSV
36	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$	96.00	XSV
37	FRONT NO PLATE	S/N	\$	60.00	XSV
38	SUNDRIES		\$	300.00	^
TOTAL SPARE PARTS		:	\$	16,258.00	
TOTAL LABOUR CHARGES		:	\$	8,532.00	
GRAND TOTAL		:	\$	24,790.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Thuan Elkhauto - 10m
: 82235769
: 31/5/22 1100
: 11/1 4days w/p OD

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT