



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0413/2022/JT
DATE : 23-May-22
WIP : 25145

Xiao Chen.

05 Rps

\$6610.08.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON SLG 8865 P

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN JEE CHING
ADDRESS : 64 FLORA DRIVE
#03-54
SINGAPORE 506860
TELEPHONE : HP +65 86862032
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100483963-05
VEHICLE NO : SLG 8865 P
MODEL CODE : A3 SEDAN 1.4 TFSI
MODEL YEAR : 24/9/2016
ENGINE NO : CZC 556125
CHASSIS NO : WAUZZZ8V5G1099224
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-May-22
PLACE OF ACCIDENT : TRAFFIC JUNCTION @ TAMPINES ROAD / KPE

55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6341 1183
EMAIL NOBA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLG 8865 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00	✓
2	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE RENEWAL OF BOTH REAR FENDERS.	S/N \$ 600.00	X
3	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N \$ 200.00	X
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND RHS 1/4 GLASS.	S/N \$ 400.00	X
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	X
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	X
SUB-TOTAL LABOUR CHARGES		: \$ 4,280.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLG 8865 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>2 days</i>	\$ 4,900.00	1000 ✓
8	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING. <i>fender : repair</i>	\$ 5,000.00	1100 ✓
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 14,372.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLG 8865 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,201.00 / Cu	1760.80
2	REAR BUMPER FIXING PARTS	1	\$ 201.00 XSV	
3	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 36.00	14.40 ✓ Payd.
4	REAR BUMPER LOCKING MECHANISM	2	\$ 67.00 X	not rec.
5	REAR BUMPER SPOILER - LH	1	\$ 264.00 / Cu	210.80
6	REAR LIGHT REFLECTOR - RH	1	\$ 46.00 X	not rec.
7	TAIL LIGHT OUTER - RH	1	\$ 974.00 / Cu	778.80
8	TAIL LIGHT TRIM OUTER - RH	1	\$ 34.00 X	not rec.
9	TAIL LIGHT INNER - RH	1	\$ 974.00 XSV	
10	TAIL LIGHT OUTER - RH	1	\$ 34.00 XSV	
11	REAR BUMPER REINFORCEMENT BEAM	1	\$ 642.00 X	not rec.
12	REAR BUMPER BRACKET - LH / RH	2	\$ 30.00	not rec.
13	REAR BUMPER GUIDE SECTION - RH LOWER	1	\$ 75.00	59.36 ✓ DM
14	REAR VENT TRIM	1	\$ 75.00 X	not rec.
15	REAR PARKING AID SENSOR - INNER / OUTER	2 196	TBC	390.24
16	REAR PARKING AID SENSOR SEAL RING	4	\$ 10.00 / nnc	8
17	REAR BUMPER WIRING SET	1	\$ 572.00 XSV	
18	REAR FENDER - RH	1	\$ 4,445.00 X	
19	REAR WINDSCREEN	1	\$ 905.00 XSV	
20	QUARTER WINDOW - RH	1	\$ 635.00 XSV	
SUB TOTAL SPARE PARTS		:	\$ 12,220.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLG 8865 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	PRIMER	2	\$ 44.00	XSL
22	GROMMET	2	\$ 38.00	XSL
23	FUEL INSERT	1	\$ 100.00	XSL
24	REAR WHEEL HOUSING LINER - RH	1	\$ 260.00	XSL
25	ARYLIC SEALANT	S/N	\$ 180.00	XSL
26	CAVITY WAX	S/N	\$ 140.00	XSL
27	STONE CHIP	S/N	\$ 180.00	XSL
28	METAL FILLER POWDER	S/N	\$ 280.00	XSL
29	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	XSL
30	1/4 GLASS SEALANT	S/N	\$ 100.00	XSL
31	SUNDRIES		\$ 400.00	1,15.68 ✓
TOTAL SPARE PARTS		:	\$ 14,142.00	
TOTAL LABOUR CHARGES		:	\$ 14,372.00	
GRAND TOTAL		:	\$ 28,514.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Thevan @ Lkhauto.com
SURVEYED DATE : 31/5/22 1000
AUTHORISED DATE :
EXCESS COST : Plp 4 day swp OD
LIABILITY :
REMARKS : 25 kyp fls.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT