

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22005234/UPA3Q2**Date:** 27/07/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle No : SLH8377B **Insured Vehicle No :** GBJ5266R

Date of Loss: 29/05/2022 Nature of Claim: TP Claim No: MFL2022D0002845

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH8377B**
 Make & Model: VOLKSWAGEN GOLF, 1.2 TSI (A) Engine No: CYV114942
 Reg. Date: 21/11/2016 (Man. Year: 2016) Chassis No: WVVZZZAUZGW242406
 Colour: Silver Odometer: 94938 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,153.92	1,835.30	8,318.62	81.93
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,920.00	810.00	2,110.00	72.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,084.92	2,656.30	10,428.62	79.70
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	13,084.92	2,050.00	11,034.92	84.33
+ GST 7.00/7.00% (S\$)	915.94	143.50	772.44	84.33
Nett Amount (S\$)	14,000.86	2,193.50	11,807.36	84.33
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,414.95		
Global Sum Settlement (S\$)		2,410.00		

INSPECTION

Date of Assignment: 02/06/2022 Present Location: Car City Auto Centre Pte Ltd (HQ)
 Date Inspected: 06/06/2022 Inspected At: Car City Auto Centre Pte Ltd (HQ)
 Estimated Period of Repair: 3.0 days Blk 9006 #01-198, Tampines Street 93
 Singapore 528840

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2022)
Parts:	144	VOLKSWAGEN GOLF 1.2 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH8377B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Not Necessary	2,399.70 FL	*- FL
2	1		*LOGO GOLF	Not Necessary	250.17 FL	*- FL
3	1		*LOGO 180 TSI	Not Necessary	239.81 FL	*- FL
4	1		*TAILLAMP RH	Not Necessary	690.99 FL	*- FL
5	1		*TAILLAMP LH	Not Necessary	690.99 FL	*- FL
6	1		*REAR BUMPER	Deformed / Torn	1,500.89 FL	*1,500.89 FL
7	1		*REAR BUMPER RETAINER RH	Not Necessary	130.17 FL	*- FL
8	1		*REAR BUMPER RETAINER LH	Not Necessary	130.17 FL	*- FL
9	1		*REAR BUMPER BRACKET RH	Not Necessary	130.17 FL	*- FL
10	1		*REAR BUMPER BRACKET LH	Not Necessary	130.17 FL	*- FL
11	1		*REAR BUMPER CENTER BRACKET	Not Necessary	260.71 FL	*- FL
12	1		*REAR BUMPER LOWER	Grazed	900.97 FL	*388.90 FL
13	1		*REAR BUMPER REINFORCEMENT	Repair	999.49 FL	*- FL
14	1		*REAR WEATHER STRIP	Not Necessary	700.17 FL	*- FL
15	1		*REAR END PANEL	Repair	1,699.79 FL	*- FL
16	2		*SEALANT	Not Necessary	40.00 FS	*- FS
17	1		*REVERSE SENSOR	Serviceable	300.00 FS	*- FS
18	1		*REAR NUMBER PLATE	Scratched	45.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,239.36	1,929.79
- List Item Discount on L Items 10.00/5.00% (\$)	1,085.44	94.49
Total Parts (\$)	10,153.92	1,835.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT,ALIGN,REPLACE TAILGATE,REAR BUMPER,REAR END PANEL,TYRE WELL,REINFORCEMENT AND AFFECTED AREA	New	1,200.00	300.00
2	TO PUTTY AND RESPRAY PAINT ON TAILGATE,REAR BUMPER,REAR END PANEL,TYRE WELL,REINFORCEMENT AND AFFECTED AREA	New	1,200.00	400.00
3	TO APPLY TUFF KOTE	New	100.00	0.00
4	TO REMOVE AND REFIT UPHOISTERY AND SEAT TO ASSIST WORK	New	200.00	60.00
5	TO REMOVE AND INSTALL REVERSE SENSOR AND CHECK WIRING	New	100.00	50.00
6	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	0.00
Gross Labour Cost (\$\$)			2,920.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >