

Vehicle Damage Assessment Report for [SLH8377B]

Estimate Created: 01/06/2022 14:11 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 16/07/2022 02:40 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Volkswagen	Model	Golf
Engine Type			
License Plate Number	SLH8377B	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- To LKK, recommended lump sum at \$2050.00 with 3 days for repair.

Note: Repair job only done on rear bumper and bootlid, not require to remove and refit upholstery and seat.

Insurlogic 1 (16/07/2022 02:37)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
REAR BUMPER		1	1500.89	-5.00 %	1,425.85
REAR BUMPER LOWER		1	388.90	-5.00 %	369.46
REAR NUMBER PLATE		1	40.00	0.00 %	40.00
Parts Subtotal					1,835.31

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
REPLACE REAR BUMPER AND ADJUST TAILGATE	RnR	300.00	0.00 %	300.00
REMOVE AND INSTALL REVERSE SENSEOR AND CHECK WIRING	RnR	50.00	0.00 %	50.00

Paint

Description		Paint Type	Cost	Markup/Disc %	Price
REAR BUMPER		Full spray	200.00	0.00 %	200.00
TAILGATE		Full spray	200.00	0.00 %	200.00
Labor Rate		S\$ 50 / Hour	General Labor Subtotal		350.00
			Paint Labor Subtotal		400.00
			Labor Subtotal		750.00

Summary

Repair Cost	2,585.31
Discount(21 %)	(535.30)
	2,050.01
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	2,050.01