

Car City Auto Centre Pte Ltd (Co.Reg.No:200719980C)

Blk 9006 #01-198, Tampines Street 93

Singapore 528840

Tel: 6781 0300 Fax: 6782 0300 Email: ccacpl@singnet.com.sg;carcity@singnet.com.sg

TP INSURER: India International Insurance Pte Ltd (HQ)

Singapore

Claimant Insurer: China Taiping Insurance (Singapore) Pte. Ltd.**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	TP/22035
Policy No:		Date of Loss:	29/05/2022
Vehicle Reg. No.:	SLH8377B	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	SEE KIM LIAN	Driver (Insured):	KHIN MAUNG CHIN
Make/Model:	VOLKSWAGEN GOLF, 1.2 TSI (A)	Vehicle Reg. Date:	21/11/2016
Vehicle Colour:	METALLIC SILVER		
Engine No:	CYV114942	Chassis No:	WVWZZZAUZGW242406
Odometer:	94676 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	CAR CITY AUTO CENTRE PTE LTD (HQ)		

not Authorized
Mercurius @ 12.15pm
6/6/22
2/5# 2100
3 days. Take photo After rep.

COST OF CLAIMS

	Amount
Parts	10,153.92
Miscellaneous Items	11.00
Labour	2,920.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	13,084.92
+ GST 7.00% (\$\$)	915.94
Nett Amount (\$\$)	14,000.86

This claim is handled by: ANSON SEAH SIEW JOO

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Jun 2022)

Parts: 144 VOLKSWAGEN GOLF 1.2 TSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLH8377B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE	10.00	0.00	*2,399.70 FL
2	1		*LOGO GOLF 11	10.00	0.00	*250.17 FL
3	1		*LOGO 180 TSI 11	10.00	0.00	*239.81 FL
4	1		*TAILLAMP RH 11	10.00	0.00	*690.99 FL
5	1		*TAILLAMP LH 11	10.00	0.00	*690.99 FL
6	1		*REAR BUMPER de / torn	10.00	0.00	*1,500.89 FL
7	1		*REAR BUMPER RETAINER RH 11	10.00	0.00	*130.17 FL
8	1		*REAR BUMPER RETAINER LH 11	10.00	0.00	*130.17 FL
9	1		*REAR BUMPER BRACKET RH 11	10.00	0.00	*130.17 FL
10	1		*REAR BUMPER BRACKET LH 11	10.00	0.00	*130.17 FL
11	1		*REAR BUMPER CENTER BRACKET 11	10.00	0.00	*260.71 FL
12	1		*REAR BUMPER LOWER ground	10.00	0.00	*900.97 FL
13	1		*REAR BUMPER REINFORCEMENT R	10.00	0.00	*999.49 FL
14	1		*REAR WEATHER STRIP 11	10.00	0.00	*700.17 FL
15	1		*REAR END PANEL R	10.00	0.00	*1,699.79 FL
16	2		*SEALANT 11	0	0.00	*40.00 FS
17	1		*REVERSE SENSOR S/R	0	0.00	*300.00 FS
18	1		*REAR NUMBER PLATE S/R	0	0.00	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,239.36
- List Item Discount on L Items (S\$)	1,085.44
Total Parts (S\$)	10,153.92

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

mm

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO PANEL BEAT,ALIGN,REPLACE TAILGATE,REAR BUMPER,REAR END PANEL,TYRE WELL,REINFORCEMENT AND AFFECTED AREA	New	<i>300</i>	1,200.00
2	TO PUTTY AND RESPRAY PAINT ON TAILGATE,REAR BUMPER,REAR END PANEL,TYRE WELL,REINFORCEMENT AND AFFECTED AREA	New	<i>400</i>	1,200.00
3	TO APPLY TUFF KOTE	New	<i>12X</i>	100.00
4	TO REMOVE AND REFIT UPHOISTERY AND SEAT TO ASSIST WORK	New	<i>60</i>	200.00
5	TO REMOVE AND INSTALL REVERSE SENSOR AND CHECK WIRING	New	<i>50</i>	100.00
6	TO REMOVE AND REFIT REAR WINDSCREEN	New	<i>12X</i>	120.00

Gross Labour Cost (S\$)

2,920.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

P-1889.79
5.2%
P-1795.30
S.N. 40
L-810
2645.30
202
2116.