



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 242R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	620223972R FRONT BUMPER	TO REPAIR SEE LABOUR	2,011.44	-
1	620358403R FRONT BUMPER SIDE BRACKET LH	SERVICEABLE	275.20	-
1	620347326R FRONT BUMPER SIDE BRACKET RH	SERVICEABLE	275.20	-
1	622552918R FRONT BUMPER SIDE INNER BRACKET LH	SERVICEABLE	226.60	-
1	622541628R FRONT BUMPER SIDE INNER BRACKET RH	SERVICEABLE	226.60	-
1	622540901R FRONT BUMPER LOWER LIP	SERVICEABLE	517.21	-
2	403007153R ALLOY RIM 20" INC @\$1405.72	FRONT DENTED / CUT	2,811.44	1,320.00
1	631012967R FRONT FENDER LH	TO REPAIR SEE LABOUR	774.72	-
1	620358403R FRONT FENDER SIDE BRACKET LH	SERVICEABLE	271.68	-
1	622907255R FRONT CENTRE BRACE BRACKET	SERVICEABLE	138.12	-
1	620436650R FRONT FENDER INNER PANAL OUTER	SERVICEABLE	134.40	-
1	261A24871R FRONT FOGLAMP MOULDING (CHROME)	SERVICEABLE	266.16	-
1	261520089R FRONT FOGLAMP COVER	SERVICEABLE	266.16	-
1	2843896148R FRONT BLIND SPOT SENSOR LH	SERVICEABLE	457.92	-
1	240704528R FRONT BUMPER SENSOR HARNESS WIRE	SERVICEABLE	219.72	-
1	620901789R FRONT BUMPER LOWER REINFORCEMENT GARNISH	SERVICEABLE	258.48	-
1	R764267651R FRONT ROKER PANEL GARNISH RH/LH	SERVICEABLE	622.20	-
1	760312734R REAR FENDER LH	TO REPAIR SEE LABOUR	2,635.32	-
1	R821019047R REAR DOOR LH GS4	TO REPAIR SEE LABOUR	2,190.24	-
1	R828776629R REAR PROTECTOR - LH DOOR GS4	CUT	555.96	555.96
1	R825037601R REAR DOOR LOCK RR LH M4S S4	TO REPAIR SEE LABOUR	467.28	-
1	R828382679R REAR DOOR SEAL REAR LH LOWER GS4	SERVICEABLE	151.08	-
1	R801004703R FRONT DOOR	TO REPAIR SEE LABOUR	2,294.64	-
1	R801861209R PROTECTOR - FRT RH DOOR GS4	SERVICEABLE	703.32	-
1	R805023720R DOOR LOCK MECH FRT RH GS4	TO REPAIR SEE LABOUR	467.28	-

Report Ref No. CS/AGI22005238/Kty3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	R804007634R DOOR HINGE RH FRT & RR (UPPER) GS4 M	TO REPAIR SEE LABOUR	257.64	-
1	R804218851R DOOR HINGE LH/RHM, FRT & RR (LOWER)	TO REPAIR SEE LABOUR	256.56	-
1	R804301428R DOOR CHECK FRT LH & RH GS4 M4S	SERVICEABLE	129.72	-
1	R804218851R REAR DOOR HINGE LH/RHM, FRT & RR (LOWER)	TO REPAIR SEE LABOUR	256.56	-
1	R824306566R REAR DOOR CHECK RR LH & RH GS4 M4S	SERVICEABLE	129.72	-
	LESS 10% DISCOUNT		-	-187.60
			20,248.57	1,688.36
	<b><u>SPECIAL NETT ITEMS</u></b>			
7	FRONT BUMPER CLIPS @\$7.00 (SN)	NOT NECESSARY	49.00	-
14	FRONT & BACK FENDER CLIPS @\$7.00 (SN)	NOT NECESSARY	98.00	-
			147.00	-
	<b><u>LABOUR</u></b>			
	TO RESPRAY ACCIDENT PORTION, FRONT BUMPER, FRONT & REAR FENDER LH, FRONT & REAR DOOR LH AND ALL NECESSARY ETC.		2,000.00	800.00
	TO REMOVE & REFIX FRONT BUMPER, FRONT & REAR FENDER LH, FRONT & REAR DOOR, HEADLAMP LH/RH, FOG LAMP LH/RH AND ALL NECESSARY ETC. INCLUSIVE OF THE REPAIR OF 620223972R FRONT BUMPER, 631012967R FRONT FENDER LH, 760312734R REAR FENDER LH, R821019047R REAR DOOR LH GS4, R825037601R REAR DOOR LOCK RR LH M4S S4, R801004703R FRONT DOOR, R805023720R DOOR LOCK MECH FRT RH GS4, R804007634R DOOR HINGE RH FRT & RR (UPPER) GS4 M, }		2,500.00	500.00
	R804218851R DOOR HINGE LH/RHM, FRT & RR (LOWER) AND R804218851R REAR DOOR HINGE LH/RHM, FRT & RR (LOWER). }		-	-
	TO REPLACE ALL SENSOR WIRE HARDNESS FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLAMP LH/RH & FOG LAMP LH/RH.	NOT NECESSARY	180.00	-
	TUFF KOTE AND SPRAY ANTI PROOFING.	NOT NECESSARY	150.00	-
			4,830.00	1,300.00
	<b>GRAND TOTAL</b>		<b>25,225.57</b>	<b>2,988.36</b>

Report Ref No. CS/AGI22005238/Kty3e2



<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,988.36</b>
------------------------------------	--	--	-----------------

Report Ref No. CS/AGI22005238/Kty3e2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**