

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869
 Tel: +65 6255 2288 | Fax: +65 6265 5388
 Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

Not Authorized
Phoning After Rain
2988-36
4 days

Vehicle No : SMN242R
 Make & Model : RENAULT, GRAND SCENIC IV 1.5 DCI AT
 EU6,VF1RFA00462704547

ESTIMATION REPORT

Estimation No. : E22060001
 Date : 01/06/2022

No.	Code	Description	Qty	U/P	Amt	
Section: Parts						
1		620223972R FRONT BUMPER	1.00	2,011.44	2,011.44	X
2		620358403R FRONT BUMPER SIDE BRACKET LH	1.00	275.20	275.20	X
3		620347326R FRONT BUMPER SIDE BRACKET RH	1.00	275.20	275.20	X
4		622552918R FRONT BUMPER SIDE INNER BRACKET LH	1.00	226.60	226.60	X
5		622541628R FRONT BUMPER SIDE INNER BRACKET RH	1.00	226.60	226.60	X
6		622540901R FRONT BUMPER LOWER LIP	1.00	517.21	517.21	X
7	<u>1320</u>	403007153R ALLOY RIM 20"INC	2.00	1,405.72	2,811.44	X
8		631012967R FRONT FENDER LH	1.00	774.72	774.72	X
9		620358403R FRONT FENDER SIDE BRACKET LH	1.00	271.68	271.68	X
10		622907255R FRONT CENTRE BRACE BRACKET	1.00	138.12	138.12	X
11		620436650R FRONT FENDER INNER PANAL OUTER	1.00	134.40	134.40	X
12		261A24871R FRONT FOG LAMP MOULDING (CHROME)	1.00	266.16	266.16	X
13		261520089R FRONT FOG LAMP COVER	1.00	266.16	266.16	X
14		2843896148R FRONT BLIND SPOT SENSOR LH	1.00	457.92	457.92	X
15		240704528R FRONT BUMPER SENSOR HARNESS WIRE	1.00	219.72	219.72	X
16		620901789R FRONT BUMPER LOWER REINFORCEMENT GARNISH	1.00	258.48	258.48	X
17		R764267651R FRONT ROKER PANEL GARNISH RH/LH	1.00	622.20	622.20	X
18		760312734R REAR FENDER LH	1.00	2,635.32	2,635.32	X
19		R821019047R REAR DOOR LH GS4	1.00	2,190.24	2,190.24	X
20		R828776629R REAR PROTECTOR- LH DOOR GS4	1.00	555.96	555.96	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Continue on next page...

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869
 Tel: +65 6255 2288 | Fax: +65 6265 5388
 Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Vehicle No : SMN242R
 Make & Model : RENAULT, GRAND SCENIC IV 1.5 DCI AT
 EU6,VF1RFA00462704547

Estimation No. : E22060001
 Date : 01/06/2022

No.	Code	Description	Qty	U/P	Amt
38			1.00	0.00	0.00
39			1.00	0.00	0.00
40			1.00	0.00	0.00
41			1.00	0.00	0.00

Amt S\$ 20,248.57
 Discount (0.00%) S\$ 0.00
 Subtotal S\$ 20,248.57

Section: Special nett

42		FRONT BUMPER CLIPS	<i>uu</i> 7.00	7.00	49.00 X
43		FRONT & BACK FENDER CLIPS	<i>uu</i> 14.00	7.00	98.00 X

Amt S\$ 147.00
 Discount (0.00%) S\$ 0.00
 Subtotal S\$ 147.00

Section: Labour

44		TO REMOVE & REFIX FRONT BUMPER, FRONT & REAR FENDER LH, FRONT & REAR DOOR, HEADLAMP LH/RH, FOGLAMP LH/RH AND ALL NECESSARY ETC	1.00	2,500.00	2,500.00 <i>500</i>
45		TO REPLACE ALL SENSOR WIRE HARDNESS FOR POPER FUNTION INCLUDIN ADJUSTMENT OF HEADLAMP LH/RH & FOG LAMP LH/RH	1.00	180.00	<i>uu</i> 180.00 X
46		TUFF KOTE AND SPRAY ANTI PROOFING	1.00	150.00	<i>uu</i> 150.00 X
47		TO RESPRAY ACCIDENT PORTION, FRONT BUMPER ,FRONT & REAR FENDER LH, FRONT & REAR DOOR LH AND ALL NECESSARY ETC	1.00	2,000.00	2,000.00 <i>Pool</i>

Amt S\$ 4,830.00
 Discount (0.00%) S\$ 0.00
 Subtotal S\$ 4,830.00

Remarks:
 AUTO & GENERAL INSURANCE
 DOA : 27/5/2022
 TP CLAIM

Total S\$ 25,225.57