



TRANS EUROKARS PTE LTD

27A TANJONG PENJURU, SINGAPORE 609042

FINALIZE COST OF REPAIRS

EQ INSURANCE COMPANY LTD		NAME :		WIP : 25021	
5 Maxwell Road		ADDRESS :			
#17-00 Tower Block				DATE: 8-Aug-22	
MND Complex, Singapore 069110					
ATTN. : MOTOR CLAIMS		TEL :			

VEH NO :	SMV7541P	DATE IN :		CONTACT PERSON :	JESS
CHASSIS NO :	JM6BP2SAAK1102682	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	M3 M-HYBRID	DATE REG.:	19-Oct-20		

NATURE OF WORKS								
NO	DESCRIPTION	QTY	UNIT PRICE	1st	Supp	PARTS NO	REVISED	PRICES
1	FRONT BUMPER	1	867.30	✓		MBCKA-50-031EBB	867.30	867.30
2	TAPE SEAL	2	2.40	✓		MBCKA-50-2G1A	4.80	4.80
3	TAPE SEAL	2	7.40	✓		MBDWH-50-2G1	14.80	14.80
4	AIR GUIDE LH FRT	1	68.20			MBCKB-50-A20B		68.20
5	RIVET	4	9.20	✓		MTK21-50-355	36.80	36.80
6	RETAINER GRILLE TOP LH	1	10.10			MBDGF-50-0U6B		10.10
7	GROMMET,SCREW	1	5.20	✓		MN243-50-0Z1	5.20	5.20
8	RETAINER LH FRT	1	19.50			MBCKA-50-0U0A		19.50
9	PLASE SET FRONT BUMPER LH	1	15.50			MBCKA-50-1V1A		15.50
10	RETAINER S,S ULTRASONIC	2	23.40	✓		MB0J8-67-UC6	46.80	46.80
11	HOLDER S,S ULTRASONIC SIDE	1	47.20	✓		MB0L2-67-UC5 13	47.20	47.20
12	SENSOR ULTRASONIC SIDE	1	190.00			MB0J8-67-UC1 E4		190.00
13	CHROME MOULD LH FRT	1	298.20	✓		MBCKA-50-7K0C	298.20	298.20
14	CLIP	1	9.10	✓		MGSH7-50-EB1	9.10	9.10
15	FRONT FENDER LH	1	415.90	✓		MBCJH-52-210	415.90	415.90
16	STAY FENDER LH	1	46.10	✓		MBCJH-52-240	46.10	46.10
17	MUD GUARD LH FRT	1	73.20			MBCKA-56-140		73.20
18	MUD GUARD LOWER LH FRT	1	201.10	✓		MBFWM-56-115	201.10	201.10
19	FASTENER	10	3.00	✓		MB45A-56-146A	30.00	30.00
20	FRONT GRILLE RAD TOP	1	690.80	✓		MBCKB-50-7E0D2M	690.80	690.80
21	RIVET	10	9.20	✓		MTK21-50-355	92.00	92.00
22	HEADLAMP LH	1	3,645.80	✓		MBCKV-51-040B	3,645.80	3,645.80
23	BRACKET HEADLAMP LH	1	56.20	✓		MBCKA-50-160A	56.20	56.20
24	CLIP	5	6.40	✓		MBCKA-56-145A	32.00	32.00

SUPPLEMENTARY								
NO	DESCRIPTION	QTY	UNIT PRICE	1st	Supp	PARTS NO	REVISED	PRICES

1	LABEL, CAUTION		1	3.50		MPE01-15-031	3.50		
2	LABEL, CAUTION		1	3.50		MKF49-61-439	3.50		
							TOTAL PARTS	6,547.10	6,916.60
								-	
							TOTAL PARTS COST	6,547.10	6,916.60
Labour Description									
								REVISED	PRICES
1		REPLACE FRT BUMPER, LHF FENDER. 10811					1,320.00	1,500.00	
2		SPRAY FRT BUMPER, LHF FENDER, TOP-GRILLE.					1,590.00	2,000.00	
3	MZ-BR-FRTSEN	TO TRANSFER FRONT PEDESTRIAN SENSORS.					150.00	660.00	
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.					150.00	250.00	
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.					180.00	300.00	
6	MZ-BR-SUNDRI	SUNDRIES.					-	50.00	
SUPPLEMENTARY LABOUR DESCRIPTION									
1		#N/A							
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.						TOTAL LABOUR	3,390.00	4,760.00	
						TOTAL PARTS	6,547.10	6,916.60	
						TOTAL	9,937.10	11,676.60	
						LESS EXCESS	-	-	
						TOTAL AFTER EXCESS	9,937.10		
						GST 7%	695.60	-	
						GRAND TOTAL	10,632.70	-	
						REPAIR DAYS	5.00		

TRANS EUROKARS PTE LTD

 Authorised Signature