



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|--|---|----------------|
| LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555 | | | Ref: CS3/LPC22001269/Vvy3e2-1 Date: 23/06/2022 Code: LPC2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | GBE 5965H | Veh. Inspected | PC 1949B |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | 22/22/22/VC05/025437 | Excess (\$) | 0.00 |
| | Assign From | GERALD POH | Assign Date | 02/06/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | TOYOTA HIACE HIROOF | c.c | 2982 |
| | Engine No. | HIDDEN | Year of Reg. | 2013 |
| | Chassis No. | JTFST22P500017809 | Colour | ORANGE |
| | Odometer | 843313 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 195 R15 | DUNLOP | 5 mm |
| | L/H Front Tyre | 195 R15 | DUNLOP | 5 mm |
| | R/H Rear Tyre | 195 R15 | DUNLOP | 5 mm |
| | L/H Rear Tyre | 195 R15 | DUNLOP | 5 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 08/02/2022 | Inspection Date | 23/02/2022 |
| | Survey held at | A-TEC AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVE 4 #05-27 PREMIER SINGAPORE 415875 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 6 Working Days | |