

FBN 8701K, 2018 Dec.

TP Budget Direct
VQ9A.

Honda Supra. 149 cc
MH1KB211XJK079280.

Front Number Plate.	new 20(SN)	X
Front wheel Fender.	Del'd 115	✓
Headlamp	ut 285	✓
Headlamp Cowling.	Am'd 175.	✓
Front Signal Lamp Cowling.	Am'd 165.	✓
Front Signal Lamp Outer Garnish.	108.	✓
Front Signal Lamp x 02	PH Am'd $68 \times 2 = 136.$	68.
Front Fork x 02	Yard $360 \times 2 = 720$	✓
Front Fork Underbracket.	Best 220	✓
Steering Stem.	2 pin 154	✓
Steering Core and Bearing.	95(SN)	✓
Front Wheel Rim.	Best 250	✓
Front Brake Disc.	14 130	X.
Centre Inner Garnish (Black).	Am'd 98	✓

FBN 8701K.

Balancer x 02	RH ut	35x2 = 70 35
Hand lever x 02	RH ut	38x2 = 76 38
Front Wing Mirror x 02	RH ut	55x2 = 110 55
Front Side Cowling x 02	cracked	175x2 = 350
Rear Box	NH NH	280(SN) X
Rear Box Bracket	NH m	200(SN) X
Striders.	NH	100(SN) 50(SN)
Labour		400 200
Spry Painting		400 200
Wiring.		50 30
To straighten body chassis.		250 200
Towing Charges.		40 ✓ 2326 4997

List: 2738 Labor: 670
Len 10%: 2464.20 total: 3275.20
S.N: 145 H/S: 2.6K
0A Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: