

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 8701K**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT WHEEL FENDER	DEFORMED	115.00	115.00
1	HEADLAMP	CUT	285.00	285.00
1	HEADLAMP COWLING	CRACKED	175.00	175.00
1	FRONT SIGNAL LAMP COWLING	CRACKED	165.00	165.00
1	FRONT SIGNAL LAMP OUTER GARNISH	CRACKED	108.00	108.00
2	FRONT SIGNAL LAMP @\$68.00	O/S CRACKED	136.00	68.00
2	FRONT FORK @\$360.00	DAMAGED	720.00	720.00
1	FRONT FORK UNDERBRACKET	BENT	220.00	220.00
1	STEERING STEM	NECESSARY	154.00	154.00
1	FRONT WHEEL RIM	BENT	250.00	250.00
1	FRONT BRAKE DISC	NOT NECESSARY	130.00	-
1	CENTRE INNER GARNISH (BLACK)	CRACKED	98.00	98.00
2	BALANCER @\$35.00	O/S CUT	70.00	35.00
2	HAND LEVER @\$38.00	O/S CUT	76.00	38.00
2	FRONT WING MIRROR @\$55.00	O/S CUT	110.00	55.00
2	FRONT SIDE COWLING @\$175.00	CRACKED	350.00	350.00
	LESS 10% DISCOUNT		-	-283.60
			3,162.00	2,552.40
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	20.00	-
1	STEERING CONE AND BEARING (SN)	NECESSARY	95.00	95.00
1	REAR BOX (SN)	NOT NECESSARY	280.00	-
1	REAR BOX BRACKET (SN)	NOT NECESSARY	200.00	-
1	STICKERS (SN)	NECESSARY	100.00	50.00
			695.00	145.00
<b><u>LABOUR</u></b>				
	LABOUR .		400.00	200.00
	SPRAY PAINTING.		400.00	200.00
	WIRING.		50.00	30.00
	TO STRAIGHTEN BODY CHASSIS .		250.00	200.00

Report Ref No. CS/AGI22005275/Avy3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING CHARGES.		40.00	40.00
			1,140.00	670.00
GRAND TOTAL			4,997.00	3,367.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/AGI22005275/Avy3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.