

ASS. REC. BY:

REF: C72/22005276/k+

C

ASSIGNMENT

SmG 42834

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 3757 Yr Regn: 12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon

Make: Renault Scen C.C. 1461

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 268914 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIRI-A 00761788739

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 195/55R20 R: GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 12/5/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S

The U/C / Chasals frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
14/6/22 11:15 AM	Car

Date/Time, File Pass to? ☐ : Prel. Report ☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ - RS - SI

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869
Tel: +65 6255 2288 | Fax: +65 6265 5388
Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

*Not Authorized
Repair the Paint*

11 hrs @ 1550/hr 3 days

ESTIMATION REPORT

Vehicle No : SMG4283H
Make & Model : RENAULT, GRAND SCENIC IV 1.5 DCI AT
EU6,VF1RFA00761788739
Year of Manufacture : 2018

Estimation No. : E22050015
Date : 19/05/2022

No.	Code	Description	Qty	U/P	Amt
Section: Parts					
1		620223972R FRONT BUMPER	1.00	1,748.76	1,748.76 X
2		620358403R FRONT BUMPER SIDE BRACKET LH	1.00	275.20	275.20 X
3		620347326R FRONT BUMPER SIDE BRACKET RH	1.00	275.20	275.20 X
4		622552918R FRONT BUMPER SIDE INNER BRACKET LH	1.00	226.60	226.60 X
5		622541628R FRONT BUMPER SIDE INNER BRACKET RH	1.00	226.60	226.60 X
6		622540901R FRONT BUMPER LOWER LIP	1.00	517.21	517.21 ✓
7		403007153R ALLOY RIM 20"INC	1.00	1,405.72	1,405.72 X
8		260602165R FRONT HEADLAMP LH	1.00	1,034.16	1,034.16 ✓
9		269257264R FRONT HEADLAMP BRACKET LH	1.00	192.84	192.84 X
10		269257264R FRONT HEADLAMP BRACKET RH	1.00	192.84	192.84 X
11		631012967R FRONT FENDER LH	1.00	774.72	774.72 X
12		620358403R FRONT FENDER SIDE BRACKET LH	1.00	271.68	271.68 X
13		622907255R FRONT CENTRE BRACE BRACKET	1.00	138.12	138.12 X
14		620436650R FRONT FENDER INNER PANEL OUTER	1.00	134.40	134.40 X
15		625005785R FRONT SUPPORT PANEL	1.00	1,293.36	1,293.36 X
16		261A24871R FRONT FOGLAMP MOULDING (CHROME)	1.00	266.16	266.16 X
17		261520089R FRONT FOGLAMP COVER	1.00	266.16	266.16 X
18		253A49995R FRONT PARKING SENSOR	1.00	291.60	291.60 X
19		2843896148R FRONT BLIND SPOT SENSOR RH	1.00	457.92	457.92 X
20		240704528R FRONT BUMPER SENSOR HARNESS WIRE	1.00	219.72	219.72 X
21		620363937R FRONT RADIATOR TOP GARNISH	1.00	502.08	502.08 X

Continue on next page...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Vehicle No : SMG4283H
Make & Model : RENAULT, GRAND SCENIC IV 1.5 DCI AT
EU6,VF1RFA00761788739
Year of Manufacture : 2018

Estimation No. : E22050015
Date : 19/05/2022

No.	Code	Description	Qty	U/P	Amt
22		620901789R FRONT BUMPER LOWER REINFORCEMENT GARNISH	<i>Ph</i> 1.00	258.48	258.48 X
23		620901789R FRONT BUMPER LOWER REINFORCEMENT GARNISH	<i>ln</i> 1.00	285.48	285.48 X

Amt S\$ 11,255.01
Discount (0.00%) S\$ 0.00
Subtotal S\$ 11,255.01

Section: Special nett

24		FRONT BUMPER CLIPS	<i>na</i> 7.00	7.00	49.00 X
25		FRONT FENDER CLIPS	<i>na</i> 7.00	7.00	49.00 X
26		RADIATOR TOP GANNISH CLIPS	<i>na</i> 10.00	7.00	70.00 X

Amt S\$ 168.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 168.00

Section: Labour

27		TO REMOVE & REFIX FRONT BUMPER , FRONT FENDER LH/RH ,HEADLAMP LH/RH, FOGLAMP LH/RH AND ALL NECESSARY ETC	1.00	1,500.00	1,500.00 <i>1500</i>
28		TO REPLACE ALL SENSOR WIRE HARDNESS FOR POPER FUNTION INCLUDIN ADJUSTMENT OF HEADLAMP LH/RH & FOG LAMP LH/RH	1.00	180.00 <i>na</i>	180.00 X <i>200</i>
29		TUFF KOTE AND SPRAY ANTI PROOFING	1.00	150.00 <i>na</i>	150.00 X
30		TO RESPRAY FRONT ACCIDENT PORTION, BUMPER ,AND FENDER LH/RH	1.00	1,200.00	1,200.00 <i>4000</i>
31			1.00	0.00	0.00

\$14,453.01

Continue on next page...