

Kenneth

REF: 0121 220052731K2y3

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. SNM22D203863C02


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1-B1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time Action / Instruction

08/06/22@2.51pm revised to So Chow by email.

Kenneth finalised final fig \$4298.20, 2 days. (Red \$4088.50, 49%)

Veh No: SMT 3366R Yr Regn: 04, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mew AE200 c.c. 1991

Colour: M.D. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 27204 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WIK 2130802A 770 766

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size: F: 245/45R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 11/5/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 3/6/2022

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prell. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trlp: 1

Survey Fee:

Transportation:

S - RS - SI

Others

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

TOTAL

Report Format : MER-TP

Lump Sum / I.B.I: (\$ 4298.20



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE  
#15-08 WESTGATE TOWER  
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SJH7974H

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 11/05/2022

TP VEH REG NO : SJH7974H

## ESTIMATE

NO : QUOT202206-000004(00)

DATE : 01/06/2022

POLICY NO : 999995580

VEH REG NO : SMT3366R

MAKE/MODEL : MERCEDES BENZ E200 SEDAN  
ABG (R18 LED0

CHASSIS NO : W1K2130802A770766

ENGINE NO : 26492080034939

REG. DATE : 2020

## Estimate Repair Cost to Vehicle No : SMT3366R

Description	Quantity	Unit Price	Amount
		S\$	S\$
<b>NET PRICE</b>			
1 Rear end panel	1	1,887.00	1,887.00
2 Rear bumper	1	2,285.00	2,285.00
3 Rear bumper reinforcement	1	1,008.00	1,008.00
4 Rear bumper centre inner frame	1	330.00	330.00
5 Rear bumper lower spoiler	1	365.00	365.00
6 Rear bumper lower chrome	1	390.00	390.00
7 Rear bumper reverse sensor	1	318.00	318.00
8 Rear bumper clips	15	12.00	180.00
			6,763.00
		Less 10%	676.30
			6,086.70
<b>LABOUR</b>			
9 To remove and refit rear bumper sensor	1	100.00	100.00
10 To check and rectify wiring system	1	80.00	80.00
11 To panel beat and straighten rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
12 To putty and spray paint on affected areas	1	1,000.00	1,000.00
13 To apply rust-proofing on replaced and repaired panels	1	120.00	120.00
			2,300.00

TOTAL S\$ 8,386.70

ADD GST @ 7% 587.07

GRAND TOTAL S\$ 8,973.77

SINGAPORE DOLLAR EIGHT THOUSAND NINE HUNDRED SEVENTY-THREE AND CENTS SEVENTY-SEVEN ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	12/05/2022 04:56 (SGT)
Date of Accident	11/05/2022 07:57 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	Tampines ave 10
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SMT3366R

### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD
Company Reg No	1XXXXXX78Z
Email Address	derrick.lee@mercedes-benz.com
Mobile Phone No	(Phone) +65-68498118
Alternative Phone No	(Office) +65-68498118

### VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E200
Variant	SEDAN AVG (R18 LED)
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1991

### INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999995580
Cover Note Number	-


### DRIVER

Name of Driver	HARI RAMANATHAN
NRIC No	SXXXX254Z



A - SMT3366R

B - SJH7974H



VERIFIED BY AJAX MARS (ARC)  
REPORTING OFFICER  
MOHAMED SHARIL BIN SATAR

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: