



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SJH7974H

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 11/05/2022

TP VEH REG NO : SJH7974H

ESTIMATE

NO : QUOT202206-000004(00)

DATE : 01/06/2022

POLICY NO : 999995580

VEH REG NO : SMT3366R

MAKE/MODEL : MERCEDES BENZ E200 SEDAN
ABG (R18 LED0

CHASSIS NO : W1K2130802A770766

ENGINE NO : 26492080034939

REG. DATE : 2020

Estimate Repair Cost to Vehicle No : SMT3366R

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Rear end panel	1	1,887.00	1,887.00
2 Rear bumper	1	2,285.00	2,285.00
3 Rear bumper reinforcement	1	1,008.00	1,008.00
4 Rear bumper centre inner frame	1	330.00	330.00
5 Rear bumper lower spoiler	1	365.00	365.00
6 Rear bumper lower chrome	1	390.00	390.00
7 Rear bumper reverse sensor	1	318.00	318.00
8 Rear bumper clips	15	12.00	180.00
			6,763.00
		Less 10%	676.30
			6,086.70
LABOUR			
9 To remove and refit rear bumper sensor	1	100.00	100.00
10 To check and rectify wiring system	1	80.00	80.00
11 To panel beat and straighten rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
12 To putty and spray paint on affected areas	1	1,000.00	1,000.00
13 To apply rust-proofing on replaced and repaired panels	1	120.00	120.00
			2,300.00

TOTAL S\$ 8,386.70

ADD GST @ 7% 587.07

GRAND TOTAL S\$ 8,973.77

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

SINGAPORE DOLLAR EIGHT THOUSAND NINE HUNDRED SEVENTY-THREE AND CENTS SEVENTY-SEVEN ONLY