



Boxfresh Pte Ltd

7030 Ang Mo Kio Ave 5 #06-49

Northstar @AMK Singapore 569880

Tel : 64585441 Fax : 64553470

Vehicle No : SBS3503Y

Accident date : 11th May 2022

Model No : Volvo

Registered owner : Go Ahead Singapore Pte Ltd

B9tl

Date of Estimate : 02/06/22

My Ref : BF-IC-1066

Total Charge

Parts changed (Total 2 days of repair)

- a) Replace engine door panel P/N:A12-02429
- b) Replace door latch DEL00298 (2 pcs)

S\$ 1066.88

S\$ 280.84

140.42 ✓

Subtotal : S\$ 1347.72

140.42

-10%

126.37

Parts Repair and Labour

- c) Repair O/S front corner bumper
- d) Repair area surrounding engine door
- e) Sand , putty and make good surface of affected parts
- f) Painting of all new and affected parts.

BOXFRESH PTE LTD

WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611

OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880

T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg



Subtotal : S\$ 800 ✓

Total Charge S\$ 2147.72 P/P - 926.37

GST S\$ 150.34

Total Bill S\$ 2298.06

Steve CLKK)

3/6/22, 11:30

W R

2 Lyr

P/P

W R L

Steve.chen@IKKauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to market survey
- Third party survey is on a "no liability" basis
- No legal liability for any survey
- Supplementary work is subject to company approval
- is subject to final approval by the company

Acknowledged by Repairer

Signature:

Date:

BOXFRESH PTE LTD

WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611

OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880

T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg