

Steve

CS/CN72 0052781Ety3

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SBS 3503Y Yr Regn: 1Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: VOLVO B9TL c.c. 9364Colour: NAVY - COLO A/C: Insured / Std / Nil / NASp. Reading: 439496 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: YV384P979 GA17469

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295/80R22.5R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or .

Front

Rear

R/Bal. U mm R/Bal. 4 mmL/Bal. U mm L/Bal. 4 mmD.O.A. 11/5/77 D.O.I. 3/6/77Survey held at Boxfresh

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Ne GIA report

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.B.E. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL



Boxfresh Pte Ltd

7030 Ang Mo Kio Ave 5 #06-49

Northstar @AMK Singapore 569880

Tel : 64585441 Fax : 64553470

Vehicle No : SBS3503Y

Accident date : 11th May 2022

Model No : Volvo

Registered owner : Go Ahead Singapore Pte Ltd

B9tl

Date of Estimate : 02/06/22

My Ref : BF-IC-1066

Total Charge

Parts changed (Total 2 days of repair)

- a) Replace engine door panel P/N:A12-02429
- b) Replace door latch DEL00298 (2 pcs)

S\$ 1066.88 XR

S\$ 280.84

140.42 ✓

Subtotal : S\$ 1347.72

Parts Repair and Labour

- c) Repair O/S front corner bumper
- d) Repair area surrounding engine door
- e) Sand , putty and make good surface of affected parts
- f) Painting of all new and affected parts.

BOXFRESH PTE LTD

WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611

OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880

T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg



Subtotal : S\$ 800 ✓
Total Charge S\$ 2147.72
GST S\$ 150.34
Total Bill S\$ 2298.06

Steve (LKK)
3/6/22, 11:30a

W R

2 Lys
P/P

W R L

Steve.chen@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "quote only" basis
- No illegal modification to be used
- Supplementary work is subject to prior approval and is subject to final approval by the insurance company

Acknowledged by Repairer

Signature:

Date:

BOXFRESH PTE LTD

WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611

OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880

T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg