

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG122005282/ENY3E2

Date: 12/07/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SBS3373E **Insured Vehicle No :** YN4983S
Date of Loss: 25/05/2022 Nature of Claim: TP Claim No: CDMCG22001046

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS3373E**
Make & Model: VOLVO B9TL, 9.4 D (A) Engine No: D9191513
Reg. Date: 03/01/2014 (Man. Year: 2013) Chassis No: YV3S4P928EA163525
Colour: Multi-colour Odometer: 543193 km
Engine Capacity: 9364 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4/4 mm
Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,262.90	2,036.61	226.29	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	325.00	325.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,912.90	2,361.61	551.29	18.93
+ GST 7.00/7.00% (S\$)	203.90	165.31	38.59	18.93
Nett Amount (S\$)	3,116.80	2,526.92	589.88	18.93

INSPECTION

Date of Assignment: 02/06/2022
Date Inspected: 03/06/2022 Inspected At: Tower Transit Singapore Pte Ltd (HQ)
21 Bulim Drive, Bulim Bus Depot
Singapore 648170
Estimated Period of Repair: 1.0 days

Adjuster: CHEN TSUE YEE

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Jul 2022)	
Parts:	N/A	VOLVO B9TL 9.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS3373E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NSF MIRROR ARM COMPLETE WITH MEKRA MISSOR ASSY	Broken	2,182.90 F	*2,182.90 FL
2	2		*REFLECTOR STICKER	Necessary	80.00 F	*80.00 FL
					Sub Total (S\$)	2,262.90
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00
					Total Parts (S\$)	2,036.61

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE ITEM NOS 1 & 2	New	650.00	325.00
			Gross Labour Cost (\$\$)	325.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >