

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0123/2022
DATE : 10-MAY-2022

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MS ZHANG XIA
ADDRESS : -

S(-)
TELEPHONE NO : -

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GW4346Y
VEHICLE NO : SJY9803R
MODEL CODE : BMW
MODEL/YEAR : BMW MODEL
ENGINE NO : BMW 120I
CHASSIS NO : WBAUL52020VL55285
MILEAGE : 1 KM
DATE IN : 10/05/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 29/04/2022

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJY9803R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	CHECK ELECTRONIC	240.00	
2	ZZ/002	RENEW RH WING MIRROR ASSY	390.00	
3	ZZ/003	S/PAINT WING MIRROR COVER	300.00	
4	ZZ/004	REMOVE TRAIMBOARD FINISHER TO ASSIST REPAIR	120.00	
TOTAL LABOUR CHARGES			1050.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJY9803R

		DAMAGED PARTS & PRICES			REMARKS
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	
1	MIRROR(HEATED) GLASS	5116 725 2893			211.00
2	SUNDRIES	NPN			10.00
3	R/F MIRROR COVER	5116 722 9262			116.00
4	R/F MIRROR ASSY	5116 728 2026			626.00
SUB TOTAL			0.00	0.00	963.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			0.00	0.00	0.00
GRAND TOTAL			0.00	0.00	963.00
OVERALL TOTAL			963.00		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJY9803R

TOTAL LABOUR CHARGES	1050.00
TOTAL SPARE PARTS CHARGES	963.00

GRAND TOTAL	2013.00 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	: -
SURVEYED DATE	: 01/06/2022
AUTHORIZED DATE	: 01/06/2022
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	: CHINA TAIPING (BASED ON INS. OFFER 50-50)

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.