



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22005289/Uvy3q2	
			Date: 07/09/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMV 4799H	Veh. Inspected	SLS 2369G
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2201903/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	02/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	PEUGEOT 3008 (A)	c.c	1199
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	VF3MRHNYWHS194086	Colour	GREY
	Odometer	66624 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/65 R17	PIRELLI	6 mm
	L/H Front Tyre	215/65 R17	PIRELLI	6 mm
	R/H Rear Tyre	215/65 R17	PIRELLI	6 mm
	L/H Rear Tyre	215/65 R17	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR , FRONT PORTION & REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/06/2022	Inspection Date	03/06/2022
	Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		20 Working Days	