

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan Fax : 6346 7213

Email: shawn7530@hotmail.com

3 Jun 2022

Vehicle No.: SLS 2369 G

Model: Peugeot 3008

front 5 day
Rear 15 days.

not Authorized
del
3/6/22

2/5 \$28,500/
20 days.

QTY	List Items	DESCRIPTION	AMT S\$
1	Front headlamp -RH	holder one 2916	\$ 3,675.00
1	Front headlamp module	11	\$ 810.00 X
1	Front grille	Cne	\$ 525.00
1	Front grille inner	Cne	\$ 462.00
1	Front grille logo	11	\$ 147.00 X
1	Front bumper	20 / Torn 1450	\$ 1,785.00
1	Front bumper centre grille	11	\$ 396.00 X
1	Front bumper fog lamp o/s	Cne	\$ 315.00
1	Front bumper fog lamp cover o/s	Torn	\$ 135.70
1	Front bumper fog lamp chrome moulding	11	\$ 100.70 X
1	Front bumper inner sponge	Torn 220-70	\$ 285.00
1	Front bumper lower garnish	D.S 485.00	\$ 650.00
1	Front bumper reinforcement	3uf 550.00	\$ 630.00
4	Front bumper PDC sensors	standard 225 x 2 = 450	\$ 1,260.00 2 pcs
1	Front bumper side grille o/s	Torn 166	\$ 210.00
2	Front bumper side retainers	o/s Cne 85	\$ 170.00 1 pc
1	Front bumper tow hook cover	R	\$ 63.00 X
1	Front fender -RH	R	\$ 540.00 X
1	Front fender inner shield	11	\$ 189.50 X
1	Front fender wheel arch garnish	Torn	\$ 297.00
1	Front support panel	Cne	\$ 876.50
1	Front support panel top garnish	Cne	\$ 325.70
2	Front safety belts	Activated 945 x 2 = 1890	\$ 4,630.00
2	Front seat belt guns	Activated 480 x 2 = 960	\$ 1,330.00
2	Front seat belt buckles	Activated 550 x 2 = 1100	\$ 1,270.00
2	Rear side seat belts	Activated 945 x 2 = 1890	\$ 5,470.00
1	Rear centre seat belt	Activated 945	\$ 1,839.60
3	Rear seat belt buckles	Activated 550 x 3 = 1650	\$ 1,905.00
1	Roof top panel	R	\$ 1,150.00 X
1	Rear windscreen glass	shipped 1600	\$ 1,885.00
2	Rear windscreen inner side garnishes	11	\$ 650.00 X
1	Rear windscreen inner seal	Rear	\$ 85.00
2	Rear windscreen side garnishes - black	M.S.C. 235	\$ 880.00 1 pc
1	Rear tailgate	welded / Cne 2080	\$ 1,850.00
2	Rear tailgate dampers	11	\$ 284.00 X
2	Rear tailgate hinges	Torn	\$ 112.00
1	Rear tailgate inner trim board	Re / Cne	\$ 312.00
			\$ 37,500.70

Rear have strong impact trigger the seatbelt.

List Items

1	Rear tailgate lamp	C/A		\$	578.00	✓
1	Rear tailgate inner lock	Tw1		\$	245.00	✓
1	Rear tailgate lock catch	11		\$	86.00	X
1	Rear tailgate logo	new		\$	85.00	✓
1	Rear tailgate outer garnish	C/A		\$	585.00	✓
1	Rear tailgate rubber	Tw1		\$	146.00	✓
1	Rear tailgate "3008" emblem	new		\$	85.00	✓
1	Rear tailgate "PURE TECH" emblem	new		\$	80.00	✓
1	Rear tailgate third brake lamp	11		\$	345.00	X
1	Rear tailgate top spoiler	R		\$	765.00	X
1	Rear wiper arm	11		\$	285.00	X
1	Rear wiper motor	Daye		\$	435.00	✓
2	Rear taillamps	CM		\$	1,572.00	✓
2	Rear taillamp lower brackets	CM		\$	178.00	✓
1	Rear end panel	B.O.D.D		\$	865.00	✓
1	Rear end panel inner garnish	Tw1		\$	192.00	✓
1	Rear bumper	D.S		\$	1,455.00	✓
2	Rear bumpers -side	N/S M O/S R	600	\$	1,350.00	1 PC
2	Rear bumper brackets	N/S Tw1	82	\$	164.00	1 PC
1	Rear bumper chrome moulding	B.O.D	385	\$	685.00	✓
2	Rear bumper lower side grilles	T/S R		\$	310.00	✓
2	Rear bumper reflectors	N/S R O/S R M	118	\$	236.00	1 PC
1	Rear bumper reinforcement	D.S		\$	685.00	✓
2	Rear bumper side retainers	Tw1/CM		\$	130.00	✓
1	Rear bumper tow hook cover	11		\$	28.00	X
1	Rear bumper undercover	11		\$	325.00	X
4	Rear bumper PDC sensors	shubh	225 x 4 = 900	\$	1,260.00	✓
1	Rear number plate lamp (1 set)	11		\$	96.00	X
1	Rear spare tyre board	11		\$	482.00	X
1	Rear spare tyre panel	R		\$	1,485.00	X
1	Rear taillamp housing panel 11	D		\$	685.00	✓
1	Rear exhaust silencer	11		\$	985.00	X
2	Rear exhaust mountings	11		\$	90.00	X
1	Rear exhaust heat shield	11		\$	185.00	X
2	Rear fender inner trims	RE/TOR		\$	446.00	✓
2	Rear fender wheel arch garnishes	DE/TOR		\$	760.00	✓
2	Rear fender top rear chromes	N/S R O/S R M	250	\$	710.00	1 PC
				\$	56,579.70	
				Less 10%	\$	5,657.97
				\$	50,921.73	

Special Nett Items

1	Front bumper clip (1 set)	new	\$	80.00	50
1	Front number plate with holder	SCR	\$	50.00	40
1	Front fender inner shield clip (1 set)	11	\$	45.00	X
1	Rear windscreen sealant	new	\$	80.00	40
1	Rear bumper clip (1 set)	new	\$	80.00	50
1	Rear wiper blade	11	\$	48.00	X
1	Rear number plate with holder	11	\$	50.00	X
1	Rear reverse camera	SVC	\$	550.00	X
1	Rear view camera	MIS	\$	650.00	400
			\$	1,633.00	

S/N.

Labour Charges

1	To check wiring and reset headlamps focusing.	F 80-15'	\$	80.00	
2	To remove, replaced damaged lamps and check up rear wiring.	R 80-15-	\$	80.00	330
3	To remove and refit inner garnishes.	Rer	\$	180.00	100
4	To remove and refit rear reverse sensor and camera.	Rer	\$	180.00	50
5	To transfer rear tailgate mechanism and wiring assembly.	Rer	\$	120.00	80
6	To remove, refit air-con condenser, refill gas & conduct leakage test.	Full	\$	180.00	100
7	To remove and refit rear windscreen glass.	Rer	\$	180.00	120
8	To remove, refit and replace exhaust silencer and mountings.	Rer	\$	150.00	X
9	To apply undercoating.	Rer	\$	300.00	60
10	Panel beating.	F-1000-500	\$	2,500.00	500
11	To re-spray painting on the affected areas.	Rer 1000-1000	\$	2,400.00	1600
12	To diagnose erase fault memory after repair.	F-1000-500 Rer 1000-1100	\$	500.00	✓
			\$	6,850.00	

Grand Total : \$ 59,404.73

P- 34617.60
102
P- 31155.84
S.N- 580
L- 4140
35875.84
292
28700.

33787.6

LKK Auto Consultants hence notify the Repairer of the following:

- To ensure before/after work, painting
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- That any survey is on a "Without Prejudice" basis
- The legal responsibility is allowed
- Supplementary claim(s) must be reviewed and is subject to final approval from Insurance Company

Authorised by Repairer
Signature:
Date: