



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMP8080C

ECICS Limited

Motor Claims Department
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600
63374779

Vehicle & Document Information

WIP No 57160
Reg No/Reg Date SMP8080C / 23/02/2018
Date In/Mileage 20/06/2022 / 42316
Chassis No WDC1569422J471808
Engine No 27091031527836
Make/Model MB/MB GLA 180 (X156) "FACELIFT"
Colour/Trim 027 787 Mountain Gr/ 043 381 MaringaFabr

Account No	Terms	Date/Time Printed	CSE	Operator
WE000073	Credit	29/06/2022/ 10:01	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : DMPHQ22-001571 // 29-5-2022 DRIVE IN/TP VEH NUMBER : 30-5-2022 // SMM6546E - ECICS DATE IN/DATE SURVEY: 20-6-2022 // STEVE - L.K.K DIRECT SETTLEMENT BY: 15-6-2022 // LIU CHUN CHEONG - ECICS				
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				960.00
A BPIRES RESpray REAR BUMPER			0.05	800.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				120.00
X BOTTOM BLACK TRIM BUMPER	1.00	596.27	00.00	596.27
X REAR BOTTOM TRIM BUMPER	1.00	1052.97	00.00	1052.97
X FOOT STEP PLATE	1.00	217.60	00.00	217.60

Confirmed & accepted by

Nett 4,126.84
7% GST on 4126.84 288.88

Authorized signatory and company stamp

Total Payable 4,415.72

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg