

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ganesh Sinathambi

Date: 04 May 2023

Preliminary Advice

Vehicle No	: SJR7311T	Accident Date	: 31/05/2022
Make	: TOYOTA VIOS	Policy No.	: A29128153QMX
Assignment Date	: 03/06/2022	Excess	: S\$500.00
Date of Inspection	: 03/06/2022	Est. Duration of Repair	: 12
Inspection At	: AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ) 38 WOODLANDS INDUSTRIAL PARK E1, #05-18 SINGAPORE 757700		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,610.60 (inclusive supp \$2,419.40)
Revised Amount	:S\$	10,560.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,560.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	5,577.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,423.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 (x) Part-by-Part repair
 () Lump Sum repair
- (x) The above survey was conducted on a 'without prejudice' basis.
 Kindly approve supplementary.