



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|--|--|
| CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | | Ref: CS3/CTI22001305/Vvy3n2-1 Date: 21/06/2022 Code: CTI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SMJ 9077M | Veh. Inspected | SKA 5420C | |
| Policy No. | DMPCSNW00077612100 | Coverage (\$) | 0.00 | |
| Claim No. | SNM22D201002/C02 | Excess (\$) | 0.00 | |
| Assign From | JACQUELINE TAN | Assign Date | 03/06/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | TOYOTA VELLFIRE 2.5 | c.c | 3456 | |
| Engine No. | HIDDEN | Year of Reg. | 2011 | |
| Chassis No. | GGH208038110 | Colour | WHITE | |
| Odometer | 148846 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 245/45 R18 | PIRELLI | 5 mm | |
| L/H Front Tyre | 245/45 R18 | PIRELLI | 5 mm | |
| R/H Rear Tyre | 245/45 R18 | PIRELLI | 5 mm | |
| L/H Rear Tyre | 245/45 R18 | PIRELLI | 5 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 10/02/2022 | Inspection Date | 14/02/2022 | |
| Survey held at | STK AUTO (S) PTE LTD 8 KAKI BUKIT AVE 4 #03-21 PREMIER@KAKI BUKIT SSINGAPORE 415875 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 7 Working Days | |