



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: KHONG LYNN			Ref: CS/ASM22005313/Vcy3m4 Date: 05/09/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 6432E	Veh. Inspected	SLX 6283S	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S2M042ZR	Excess (\$)	0.00	
Assign From	KHONG LYNN	Assign Date	03/06/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA CAMRY	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053BK4107033635	Colour	RED	
Odometer	134968 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	BLUEARTH	6 mm	
L/H Front Tyre	215/55 R17	BLUEARTH	6 mm	
R/H Rear Tyre	215/55 R17	BLUEARTH	6 mm	
L/H Rear Tyre	215/55 R17	BLUEARTH	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	01/06/2022	Inspection Date	06/06/2022	
Survey held at	SUN FATT MOTORS 1 KAKI BUKIT AVE 6 AUTOBAY@ KAKI BUKIT #01-47 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	