

新發摩哆 SUN FATT MOTORS

1 Kaki Bukit Ave 6 #01-47

Singapore 417883

TEL: 6741 8535 FAX: 6481 5149

sunfattmotors@gmail.com

Reg. No. 399645/00-D

Mr Tan Kian Hin

Estimates cost of repairs: SLX 6283 S

4/6/22

1pc front door glass lh
1pc front door lh
1pc front door rubber
1pc front door outer handle
1pc side mirror lh
1pc side mirror cover lh
1pc front door lower moulding lh
1pc front door lower protector lh
1pc front door inner lock
1pc front door outer top moulding
1pc front door power window regulator gear
1pc front door power window motor
1pc rear door lh
1pc rear door lower moulding
1pc rear door lower protector lh
1pc rear door top moulding
1pc rear door rubber

871.50 ⁶⁸⁰
1890.60 ¹³⁰⁰
255.80
78.20
1477.60 ¹¹⁵⁹
84.80
39.70
182.40
528.60
154.80
234.40
608.80
1640.20 ¹²⁵⁰
39.70
188.60
155.80
245.80
8677.30
2169.32
6507.98

Less 25%

To remove replace /transfer doors mechanism etc
To spray painting
To repair damages
To check wiring works

300.00 ¹⁶⁰
800.00 ⁵⁰⁰
800.00 ⁵⁰⁰
200.00 ³⁰
\$ 8607.98

52235239

616122 1645

1's 4 days

total: 5307.55

c/s A.21c

05 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

A.21c

F. 4450

RD. S

4975.80

3731.85

950

4687.85

1243745