



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909		Ref: CS/UOI22005316/Aqy3e2 Date: 13/04/2023 Code: UOI2	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	YQ 1816X
Policy No.	DHOM120047631902	Coverage (\$)	0.00
Claim No.	M12D18562206	Excess (\$)	500.00
Assign From	JOSEPHINE WONG	Assign Date	03/06/2022
2. Vehicle Particulars & Condition			
Make & Model	HINO XZU710R	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JHHUCV3HX0K032236	Colour	WHITE
Odometer	95790 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	7.00 R16	WEST LAKE	6 mm
L/H Front Tyre	7.00 R16	WEST LAKE	6 mm
R/H Rear Tyre	7.00 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	7.00 R16	BRIDGESTONE	6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	31/05/2022	Inspection Date	14/06/2022
Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147		
5a. Remarks			
	A)THE MARKET VALUE IS S\$80,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days