



# 簡福星摩多工廠

## KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

UNITED OVERSEAS INSURANCE LTD

DATE : 03-06-2022

146 ROBINSON ROAD

#02-01 UOI BUILDING

SINGAPORE 068909

VEHICLE NO. : YQ1816X

ACCIDENT DATE : 31-05-2022 09:40

THIRD PARTY REF. : SHA4164J

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE YQ1816X HINO XZU710R 14FT WIDE CAB 5T

| #           | QTY | PARTS DESCRIPTION               | AMOUNT (SG\$) |
|-------------|-----|---------------------------------|---------------|
| 1           | 1   | FRONT BODY PANEL                | 650.00        |
| 2           | 1   | FRONT BODY PANEL STICKER (HINO) | 52.00         |
| 3           | 1   | FRONT BODY PANEL STICKER (300)  | 52.00         |
| 4           | 1   | FRONT GRILLE                    | 300.00        |
| 5           | 1   | HEAD-LAMP (RH)                  | 320.00        |
| 6           | 1   | FRONT BUMPER                    | 620.00        |
| 7           | 1   | FRONT BUMPER REINFORCEMENT      | 350.00        |
| 8           | 1   | FRONT BUMPER SIDE BRACKET (RH)  | 155.00        |
| 9           | 1   | STEP GARNISH (RH)               | 85.00         |
| 10          | 1   | FRONT WINDSCREEN MOULDING       | 350.00        |
|             |     |                                 | <hr/>         |
|             |     |                                 | 2,934.00      |
|             |     |                                 | <hr/>         |
| ADD 10 %    |     |                                 | 293.40        |
|             |     |                                 | <hr/>         |
| TOTAL ( A ) |     |                                 | 3,227.40      |
|             |     |                                 | <hr/>         |

### SPECIAL NETT ITEMS

|             |   |             |       |
|-------------|---|-------------|-------|
| 1           | 1 | ERP STICKER | 10.00 |
|             |   |             | <hr/> |
| TOTAL ( C ) |   |             | 10.00 |
|             |   |             | <hr/> |

### LABOUR CHARGES

|   |   |                                 |        |
|---|---|---------------------------------|--------|
| 1 | 1 | REMOVE & REFIX FRONT WINDSCREEN | 120.00 |
| 2 | 1 | REMOVE & REFIX DASHBOARD ASSY   | 300.00 |



# 簡福星摩多工廠

## KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : YQ1816X

ACCIDENT DATE : 31-05-2022 09:40

THIRD PARTY REF. : SHA4164J

| #              | QTY | PARTS DESCRIPTION                                                                     | AMOUNT (SG\$)        |
|----------------|-----|---------------------------------------------------------------------------------------|----------------------|
| 3              | 1   | REMOVE & REFILL AIR CON GAS                                                           | 120.00               |
| 4              | 1   | REMOVE ALL NECESSARY AFFECTED PARTS FO REPAIRS, WELD/CUT, PANEL BEATING & RENEW PARTS | 600.00               |
| 5              | 1   | SPRAY PAINTING                                                                        | 600.00               |
| TOTAL ( D )    |     |                                                                                       | <hr/> 1,740.00 <hr/> |
| ESTIMATE TOTAL |     |                                                                                       | <hr/> 4,977.40 <hr/> |