



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF22005318/Rqy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1			Date:	25/10/2022
HEMMANT ROAD SINGAPORE 438675				
ATTN: HAFIZUL FARHAN			Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJU 9671A	Veh. Inspected	SDA 5551R
	Policy No.		Coverage (\$)	0.00
	Claim No.	ACS/105/009/2022/028	Excess (\$)	0.00
	Assign From	HAFIZUL FARHAN	Assign Date	03/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY 2.0 A	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MR053BK4107027477	Colour	BLACK
	Odometer	338748 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	MICHELIN	6 mm
	L/H Front Tyre	215/60 R16	MICHELIN	6 mm
	R/H Rear Tyre	215/60 R16	MICHELIN	6 mm
	L/H Rear Tyre	215/60 R16	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
	DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/05/2022	Inspection Date	17/06/2022
	Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	