



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION (TP)		Ref:	CS/SPF22005319/Kqy3e2
ACCIDENT CLAIMS SECTION(SPORE POLICE FORCE)POLICE LOGISTICS BASE (PLB)1 HEMMANT ROAD SINGAPORE 438675		Date:	23/06/2022
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 501T	Veh. Inspected	SKT 4266M
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/029	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	03/06/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA MOBILIO (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MRHDD4870FP000148	Colour	METALLIC SILVER
Odometer	470242 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/55 R16	BRIDGESTONE	6 mm
L/H Front Tyre	185/55 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	185/55 R16	BRIDGESTONE	4 mm
L/H Rear Tyre	185/55 R16	BRIDGESTONE	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/05/2022	Inspection Date	06/06/2022
Survey held at	Blk 5038 #01-405 Ang mo kio industrial Pk 2		
Repairer	MASSIVE TRADING & AUTO		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	