

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD (TP) / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMC5419Z
 at Workshop m/s: Nineham
 of _____
 Insured: SLE 95964
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMC5419Z Yr Regn: 07/11/08
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or (A)
 Make: Volkswagen GTI c.c. 1984
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp.Reading: 226069 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WVWZZZ1KZ8U029216
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/40ZNF
 R: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: LTA @ 21850
 Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / (MIC) / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 Rear 6
 R/Bal. _____ mm R/Bal. _____ mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 25/05/22 D.O.I. 02/06/22
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Rep</u>
	<u>Cor uncl 31-08-2028 LTA @ 21850</u>
<u>9/6/22</u>	<u>L/S @ 2300 informed Jeremy photo rear bumper 4920 to 4925 diffuser 4903 - 4905</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to? _____
 2) _____
 Report Format : _____
 Lump Sum / I.B.I. (\$) _____)

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
) S + RS, SI
) Photos
) Others
 TOTAL _____

NINETEEN AUTOWERKS PTE LTD

6 Tampines Street 43
 #01-97 Singapore 520436
 Tel: (65) 9674 1991
 ☒ nineteenautowerks@gmail.com

*Not Authorized
 all
 Marcus
 2/5 @ 2300
 2/6/22
 3 days*



**NINETEEN
 AUTOWERKS**

ESTIMATE

DATE: 1-Jun-22
DOA: 25-May-22
VEHICLE NO: SMC 5419 Z
MAKE & MODEL: VOLKSWAGEN GOLF GTI

DESCRIPTION	QUANTITY	AMOUNT	TOTAL
LIST ITEMS			
Tailgate	1	\$2,088.90	11 \$2,088.90 X
Tailgate logo	1	\$80.00	11 \$80.00 X
Tailgate weatherstrip	1	\$225.00	11 \$225.00 X
Rear bumper	1	\$1,436.90	before \$1,436.90 ✓
Rear bumper side retainer	2	\$120.60	11 \$241.20 X
Rear bumper centre retainer	1	\$164.30	11 \$164.30 X
Rear bumper reflector	2	\$89.00	11 \$178.00 X
Rear bumper reinforcement	1	\$552.30	11 \$552.30 X
Rear bumper diffuser	1	\$800.00	one \$800.00 ✓
Rear number plate lamp	1	\$133.00	11 \$133.00 X
Rear end panel	1	\$811.00	11 \$811.00 X
Rear end panel top garnish	1	\$225.50	11 \$225.50 X
Exhaust pipe	1	\$1,420.00	11 \$1,420.00 X
Exhaust pipe mounting	2	\$87.50	11 \$175.00 X
		Total	\$8,531.10
		Less 10%	\$853.11
			\$7,677.99

SPECIAL NETT ITEMS

Sundries	1	\$60.00	11 \$60.00 X
Rear bumper clips (set)	1	\$80.00	11 \$80.00 50
Rear end panel top garnish clips (set)	1	\$30.00	11 \$30.00 X
Rear end panel sealant	1	\$80.00	11 \$80.00 X
Reverse sensor	1	\$300.00	11 \$300.00 X
			\$550.00
	Parts Total		\$8,227.99

LABOUR CHARGES

Panel beating	300	\$1,200.00
Spray painting	500	\$1,000.00
Remove & refit exhaust pipe assy	11 X	\$200.00
Remove & refit reverse sensor and test	50	\$100.00
Check wiring system after disconnect & connect	11	\$100.00
To apply undercoating for rust roofing	11 X	\$100.00
		Labour Total
		\$2,700.00

Total Parts and Labour Cost of Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$10,927.99

2- 2236.90

*10%
 2013.21*