

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Melody Teoh

Date: 06 Jun 2022

Preliminary Advice

Vehicle No	: SLR5959P	Accident Date	: 01/06/2022
Make	: TOYOTA HARRIER	Policy No.	: DMPG21008036
Assignment Date	: 03/06/2022	Excess	: S\$700.00
Date of Inspection	: 6/6/2022	Est. Duration of Repair	:10
Inspection At	: ALAN'S UNITED AUTO PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,450.30
Revised Amount	:S\$	12,785.50
Check Items (Estimated)	:S\$	3,650.00
Total	:S\$	16,435.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	100,000.00
COE / PARF Rebate	:S\$	44,830.00
Salvage Value	:S\$	
Margin for Repair	:S\$	55,170.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Part by part repair. Kindly advised solar file insured in the policy.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .