Case Details

Case Reference Number : TAX/06/22/2004

Type of Repair : Accident Repair

Vehicle Registration Number : SHD6313S

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-18459-ID

Assigned By: Taxi Claims Manager Team

Insurance Company Name : India International Insurance Pte Ltd

Accident Date and Time: 01/06/2022 01:15 PM

Vehicle Age(In Months): -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

				SMRT Recommendation							Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace v	300-
Standard	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check ~	2. Xnn
Standard	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give 🗸	xan
Standard	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give ~	Kn
Standard	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give ~	KAN
Standard	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	0	0	Not Give •	xan
Standard	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give ✓	Kan
Standard	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give →	XAM
Standard	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Not Give ~	KM
Standard	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	•	Not Give ✓	Kan
Standard	Main			EXTENSION SUB- ASSY, LH	1	116.30	116.30	25.00	87.23	Replace	0	0	Not Give 🐱	Kan
tandard	Main			EXTENSION SUB- ASSY, RH	,	116.30	116.30	25.00	87.23	Replace	0	0	Not Give ✓	Kan
tandard	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0	Not Give 🐱	Xur
tandard	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	0	0	Not Give 🗸	Knn
tandard	Main			SEAL, HOOD TO	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give V	XXX

Total Spare Part Cost 8,429.29

Lump Sum Discount (%) 20.00

Final Spare Part Cost 6,743.43

Surveyor Total 422.55

Lump Sum Dis (%)

20

Final Sur Total 338.04

	1			OMICI RECOIL	menua	mori	the same					Surve	yor Approval	
300	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	RepairiReplace	Remarks
Standar	d Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	0	0	Not Give ~	X17
Standar	d Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Not Give ~	Kan
Standar	d Main			GRILLE SUB- ASSY	1	335.60	335.60	25.00	251.70	Replace	0	0	Not Give ~	XAA
Standar	d Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25 /	Replace ~	ner/
Standar	d Main			RETAINER, FR BUMPER, LH & RH	1	8.50	8.50	25.00	6.38	Replace	0	0	Not Give ✓	Xn
Standard	d Main			COVER, ENGINE UNDER SIDE RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Not Give ~	Xnn
Standard	d Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	0	0	Check ~	!xn
Standard	d Main			UNIT, HEADLAMP, RH	.1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check v	? X1.
Standard	Main .			COMPUTER SUB- ASSY, HEADLAMP, RH NO.1	•	486.40	486.40	10.00	437.76	Replace	0	0	Not Give ~	Kan
Standard	Main			FENDER SUB- ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair ~	R
Standard	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.68	Replace	1	39.97	Replace ~	nie 1
Standard	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0	Not Give →	Lan
Standard	Main			PAD, FR WHEEL RH	1	57.70	57.70	25.00	43.28	Replace	0	0	Not Give ~	Xm
Standard	Main			SEAL SUB-ASSY, RH	1	50.20	50.20	25.00	37.65	Replace	0	0	Not Give ~	KM
Standard	Main			PROTECTOR, FR FENDER RH	1	90.40	90.40	25.00	67.80	Replace	0	0	Not Give ~	KAN
Standard	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Give ~	
Standard	Main			SUPPORT S/A UPPER,	1	364.90	364.90	25.00	273.67	Replace	0	0	Not Give ~	Xan
itandard	Main				1	237.00	237.00	25.00	177.75	Replace	0	0	Not Give ✓	Xnn Xnn
						Total	tal Space S	C	9 400 00		9990			
							Sum Disco					Sum Dis (%)		
									STATE OF		cump :	Julii Dis (74)	20	
						Fin	al Spare Pa	art Cost	6,743.43		Fir	al Sur Total	338.04	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks	
1	Main	TO REPAIR FRONT RH PORTION	676.00	300		
Total:			676.00	300.00		

	EE, 14:30		nups.//vacsy	web.smrt.com.s	g/Estimation.aspx
	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
	Main	TO RESPRAY RIM	180.00	· XVV	
2	Main	TO RESPRAY FRONT BUMPER	378.00	200	
3	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	· Kn	
4	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	· KA	
5	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
otal:			1,296.00	400.00	

Other Cost Detail

cy Cc

rk: Th

Accir PR epai tum:

R

/T

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	· Xny	
2	Main	TO WASH AND VACUUM	60.00	· ×11	
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	20	
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	· Xan	
5	Main	TO REPLACE SUNDRY PARTS	100.00	ه ۲۷۲	
tal:			500.00	20.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,743.43	338.04
Total Labour Cost	676.00	300.00
Total Spray Painting	1,296,00	400.00
Other	500.00	20.00
Overall Total	9,215,43	1,058.04
ump Sum Repair Option	5	
ump Sum Total	9,200.00	1,050.00
urveyor Approved Amount		1,050.00
lo of Repair Days*	5	3

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Remarks		LUMP SUM REPAIR / RESURVEY AFTER PAINT PHOTO.
Surveyor Name		Rasul
Signature	-	nA
		Kar
		Save Clear

03/06/2022

14.30

Survey Date

LKK Auto Consultants hence notify

the Repairer of the following:

https://vacsweb.smrt.com.sg/Estimation.aspx

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLYMENT PARTS

Contr			1 . 1		Date of C	olle zion	
Accident Case Number		14X 06/25/2007		22/2004	Date of C	Checuon	I I
Vehic	ele No	Sal) 6313	38	Date of I	Request	04/06/2022
Vehicle	e Model	OT	(07A	PRUS 4	Number of Days to Extend (If any)		
S/N	Part Nu	mher		Part Descript	ion	Quantity	Unit Price
1	Tartiva		PINO	HEADLAMP		In	cra
b.						10 mm	
	I.		<< <p< td=""><td>lease submit photograp</td><td>ns for damaged parts:</td><td>>>></td><td></td></p<>	lease submit photograp	ns for damaged parts:	>>>	
I, (Nam	ie)						
(Positie	on)						
	mnly and si	ncerely d	eclare that	:- Supplementar	y Parts are rai	sed for replac	ement for the aforesaid
I acknowl	edge that this de	claration is to	rue and correct	t, and I make it with th	[to	be signed in fro	on making this declaration nt of an authorised witness] on who makes a false declaration is
	he damages of pe	erjury.		***************************************			
For SMRT	Staff						
Ackn	owledge By		ARC Exec	cutive / Superviso	or / SA		
App	proval By		Surve	yor / In-house St	aff		,
Part	s Ordering	SMF	RT Store / C	Contractor Supply WOC	/ Form 22 /	Form22 / PO /	WOC/ Reservation/Number

YES / NO

Date of submission

Photo Submitted