



Section A - Accident Details

Registration Number	SHD6313S
Case Reference Number	TAX/06/22/2004
Registration Date	1/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	HUANG WENXIONG
Type of Accident	Head To Side
Accident Date and Time	1/6/2022 9:15 PM
Accident Reported Date and Time	2/6/2022 11:35 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115185
Special Instruction to ARC, if any	FRONT RIGHT
Prepared Date and Time	2/6/2022 1:24 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$1,296.00	\$400.00
Total Spare Part Cost	\$8,585.84	\$2,180.46
Total Other Cost	\$500.00	\$20.00
TOTAL COST	\$11,057.84	\$2,900.46
Lump Sum Total	\$11,050.00	\$2,900.00 (L/S)
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / III
ARC / Surveyor Sign Off Date	07/06/2022 11:51 AM	07/06/2022 11:14 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP = 0 day.	LUMP SUM REPAIR / RESURVEY AFTER PAINT PHOTO .

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2206-0186	Invoice Number	
Quotation Date	17.06.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$676.00	\$300.00
Total Labour	\$676.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,296.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$500.00	\$20.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		8114547691	UNIT , HEADLAMP , RH	0.00	\$2,558.90	0.00	\$0.00	Replace	Check
		8121047020	LAMP ASSY, FOG, RH	0.00	\$910.20	0.00	\$0.00	Replace	Check
		5202147110	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Not Given
			NUMBER PLATE	0.00	\$35.00	0.00	\$0.00	Replace	Not Given
		5211947962	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace
		5212747907	COVER, FR BUMPER RH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given
		5212847906	COVER, FR BUMPER LH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given
		5211447190	BRACKET, FR BUMPER	0.00	\$99.80	0.00	\$0.00	Replace	Not Given
		5261147140	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Not Given
		5210347010	EXTENSION SUB-ASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given
		5210247020	EXTENSION SUB-ASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given
		5213247010	REINFORCEMENT FRONT LOWER	0.00	\$238.50	0.00	\$0.00	Replace	Not Given
		5261847090	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Not Given
		5339547040	SEAL, HOOD TO FR END	0.00	\$24.40	0.00	\$0.00	Replace	Not Given
		7531047060	EMBLEM ASSY FRONT	0.00	\$87.10	0.00	\$0.00	Replace	Not Given
		5311247240	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Not Given

X
X
X
X
√
X
X
X
X
X
X
X
X
X
X
X
X

