


Section A - Accident Details

Registration Number	SHD6313S
Case Reference Number	TAX/06/22/2004
Registration Date	1/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	HUANG WENXIONG
Type of Accident	Head To Side
Accident Date and Time	1/6/2022 9:15 PM
Accident Reported Date and Time	2/6/2022 11:35 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115185
Special Instruction to ARC, if any	FRONT RIGHT
Prepared Date and Time	2/6/2022 1:24 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates
Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$1,296.00	\$400.00
Total Spare Part Cost	\$8,585.84	\$2,180.46
Total Other Cost	\$500.00	\$20.00
TOTAL COST	\$11,057.84	\$2,900.46
Lump Sum Total	\$11,050.00	\$2,900.00 (L/S)
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / III
ARC / Surveyor Sign Off Date	07/06/2022 11:51 AM	07/06/2022 11:14 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP = 0 day.	LUMP SUM REPAIR / RESURVEY AFTER PAINT PHOTO .

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 17/06/2022

User ID : PohSuan

	5310147080	GRILLE SUB-ASSY	0.00	\$335.60	0.00	\$0.00	Replace	Not Given	X	NN
	5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	√	NEC
	5253550060	RETAINER, FR BUMPER, LH & RH	0.00	\$8.50	0.00	\$0.00	Replace	Not Given	X	
	5144347020	COVER, ENGINE UNDER SIDE RH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given	X	X NN
	5380147080	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair	R	
	7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	√	NEC
	5387547070	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given	X	
	5385147061	PAD, FR WHEEL RH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	X	
	5380747020	SEAL SUB-ASSY, RH	0.00	\$50.20	0.00	\$0.00	Replace	Not Given	X	
	5382747050	PROTECTOR, FR FENDER RH	0.00	\$90.40	0.00	\$0.00	Replace	Not Given	X	
	42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X	X NN
	5320247901	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Not Given	X	
	5211547050	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Check	X	
	5211647050	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given	X	
		NUMBER PLATE FRAME	0.00	\$25.00	0.00	\$0.00	Replace	Not Given	X	
	8101647690	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Not Given	X	
	5320547900	SUPPORT S/A UPPER,	0.00	\$364.90	0.00	\$0.00	Replace	Not Given	X	
Total				\$10,414.40		\$422.56				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		8114547691	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	√ CRA
Total					2,558.90		2,303.01			

2,725.57
 -20%
 2180.46
 + 300.00
 + 420.00
 2,900.46

L/S \$2,900/-

