

151G



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

- Survey by lanti khon

LKK
GBC6198J NISSAN NV200

VSKYBAM 204 0033525

			Estimated	
No	Qty	Parts Description	Parts Price	
1	1	Rear bumper assy	\$	780.00 DD
2	1	Rear bumper left bracket	\$	98.00 X NS
3	1	Rear bumper right bracket	\$	98.00 X SVC
4	1	Rear bumper left retainer	\$	85.00 ✓ CRA
5	1	Rear bumper right retainer	\$	85.00 X SVC
6	1	Rear bumper tow cover	\$	78.00 X NS
7	1	Reinforcement sponge	\$	280.00 TN
8	1	Rear boot -tailgate	\$	1,800.00 BUC
9	1	Rear tailgate rubber garnish	\$	372.20 DD
10	1	Tailgate internal trim cover	\$	385.00 X SVC
11	1	Tailgate logo nissan	\$	95.00 NEC
12	1	Tailgate holder /pull pocket	\$	95.00 X NS
13	1	Rear tailgate emblem /model	\$	105.00 ✓ XEC
14	1	Rear boot lock mechanism	\$	280.00 X SVC
15	1	Rear boot lock holder	\$	95.00 X NN
16	1	Rear end top cover	\$	375.00 ✓ AT
17	1	Antena, electrical key	\$	88.00 X NS
18	2	Rear tailgate no plate lamp	\$	65.00 X NN
19	1	Rear left taillamp	\$	550.00 X NN
20	1	Rear right taillamp	\$	550.00 X NN
21	1	Rear left corner light	\$	250.00 X NS
22	1	Rear right corner light	\$	250.00 X NS
23	1	Rear end lower tray	\$	350.00 X NN
24	2	Windscreen rubber	\$	280.00 X NS
25	1	Rear end panel	\$	900.00 X R
Sub-total Parts			\$	8,189.20



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

GBC6198J NISSAN NV200

			Estimated	
No	Qty	Parts Description	Parts Price	
<u>Special Nett Items</u>				
1	10	Rear bumper clips	\$	80.00
2	6	Rear end lower panel top garnish clips	\$	50.00
3	1	Rear end lower panel sealant	\$	120.00
4	8	Rear tailgate inner trim board clips	\$	50.00
5	6	Rear tailgate outer garnish clips	\$	50.00
6	1	Rear floor panel sealant	\$	120.00
7	1	Rear windscreen glass sealant	\$	80.00
8	3	Rear windscreen mounding	\$	320.00
9	2	Rear bumper reverse sensor	\$ 280	250.00
10	1	Rear no plate with garnish	\$	80.00
11	2	Rerve sensor	\$	500.00
Sub-total special nett			\$	1,700.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

GB6198L NISSAN NV350 200

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts, main body frame RR frame damaged	\$ 1,500.00	500
2	To putty and spray painting rear portion, boot inside out, bumper, right fender dent, main frame metal, rear end panel, gutter side panel for left and right	\$ 1,500.00	600
3	To check rear lighting and wiring.	\$ 60.00	30
4	To remove and install rear tailgate lock mechanism.	\$ 80.00	50
5	To remove & install rear windscreen glass to facilitate the repair.	\$ 150.00	80
6	To apply anti rust proofing to rear affected area including behind spare tyre area	\$ 250.00	50
7	To remove and install rear bumper reverse sensor.	\$ 80.00	30
8	To remove and install rear exhaust muffler assy.	\$ 250.00	X
9	To remove and rear internal internal trims to facilitate the repair	\$ 80.00	30
10	To remove and install rear camera to facilitate the repair	\$ 80.00	X
Total labour :		\$ 4,030.00	

5 days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: