

ASS. REC. BY:

Tayyib

REF:

CS/MSG 22005330 TVY3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLG 8469A

Policy No. 30001959671


Claims No. 275812

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBC6198J Yr Regn: 1 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV200 c.c. 1598

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSKY BAM 204 0033525

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: N / S/Rim / STD A/Rim or

Tyre Size: F: 175/70 R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 2/6/2022 D.O.I. 07/06/22

Survey held at Xin Jun.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/4/23 Lump Sum \$4150 (red 9969.20, 70%)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 12/4/23-typist

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

Rep. Format: Merimen

Lump Sum / L.S. (\$4150)

1. Name	: LKK AUTO CONSULTANTS PTE LTD	
2. Identification No. Type	: Company	
3. Identification No.	: 199607198R	Bal. : 10 months.
4. Place Of Passport Issue	: -	
5. Registered Address	: 51 UBI AVENUE 1	M.V. : \$11,000.
	: #01-25	
	: PAYA UBI INDUSTRIAL PARK	
	: SINGAPORE 408933	
6. Mailing Address	: -	
7. Vehicle No.	: GBC6198J	
8. Effective Date of Ownership	: 09 Apr 2013	
9. Original Registration Date	: 09 Apr 2013	
10. First Registration Date	: 09 Apr 2013	
11. Vehicle Type	: A50 - Goods (Closed) Van/Van Panel (Delivery)	
12. Vehicle Scheme	: Normal	
13. Attachment 1	: No Attachment	
14. Attachment 2	: -	
15. Attachment 3	: -	
16. Vehicle Make	: NISSAN	
17. Vehicle Model	: NV200 1.5L MT ABS AIRBAG 2WD 6DR	
18. Year of Manufacture	: 2011	
19. Primary Colour	: Silver	
20. Secondary Colour	: -	
21. Passenger Capacity	: 1	
22. Chassis/Trailer Chassis No.	: VSKYBAM20U0033525 / -	
23. Propellant	: Diesel	
24. Engine No./Motor No.	: K9KF276D126764 / -	
25. Engine Capacity(cc)/Power Rating(kw)	: 1461 / -	
26. Unladen Weight(kg)	: 1320	
27. Maximum Laden Weight(kg)	: 2000	
28. Open Market Value	: \$23,563.00	
29. PARF Eligibility	: No	
30. PARF Eligibility Expiry Date	: -	
31. Minimum PARF Benefit	: \$0.00	
32. IU Label No.	: -	
33. COE No.	: 2013030105000148R	
34. COE Expiry Date	: 08 Apr 2023 //	
35. COE Category	: C - Goods Vehicle & Bus	
36. Quota Premium/Prevailing Quota Premium	: \$54,989.00	
37. Actual Quota Premium/PQP Paid	: \$54,989.00	
38. Actual ARF Paid	: \$1,179.00	
39. CO2 Emission(g/km)	: 137.00	
40. Actual CEVS Rebate Utilised	: -	
41. CEVS Surcharge Paid	: -	
42. Actual Green Vehicle Rebate Utilised	: -	
43. Vehicle Lifespan Expiry Date	: 08 Apr 2033	
44. Road Tax Amount	: \$213.00	
45. Road Tax Start Date	: 09 Apr 2013	
46. Road Tax End Date	: 08 Oct 2013	
47. Remarks	: This vehicle requires side marking. To renew the COE, the Prevailing Quota Premium payable is that of Category C.	

4,582.00

151G



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

- Survey by lanti khon

LKK
GBC6198J NISSAN NV200

VSKYBAM 204 0033525

No	Qty	Parts Description	Estimated Parts Price	
1	1	Rear bumper assy	\$ 780.00	DD
2	1	Rear bumper left bracket	\$ 98.00	X NS
3	1	Rear bumper right bracket	\$ 98.00	X SVC
4	1	Rear bumper left retainer	\$ 85.00	✓ CRA
5	1	Rear bumper right retainer	\$ 85.00	X SVC
6	1	Rear bumper tow cover	\$ 78.00	X NS
7	1	Reinforcement sponge	\$ 280.00	TN
8	1	Rear boot -tailgate	\$ 1,800.00	BUC
9	1	Rear tailgate rubber garnish	\$ 372.20	DD
10	1	Tailgate internal trim cover	\$ 385.00	X SVC
11	1	Tailgate logo nissan	\$ 95.00	NEC
12	1	Tailgate holder /pull pocket	\$ 95.00	X NS
13	1	Rear tailgate emblem /model	\$ 105.00	✓ NEC
14	1	Rear boot lock mechanism	\$ 280.00	X SVC
15	1	Rear boot lock holder	\$ 95.00	X NN
16	1	Rear end top cover	\$ 375.00	✓ OUT
17	1	Antena, electrical key	\$ 88.00	X NS
18	2	Rear tailgate no plate lamp	\$ 65.00	X NN
19	1	Rear left taillamp	\$ 550.00	X NN
20	1	Rear right taillamp	\$ 550.00	X NN
21	1	Rear left corner light	\$ 250.00	X NS
22	1	Rear right corner light	\$ 250.00	X NS
23	1	Rear end lower tray	\$ 350.00	X NN
24	2	Windscreen rubber	\$ 280.00	X NS
25	1	Rear end panel	\$ 900.00	X R
Sub-total Parts			\$ 8,189.20	



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

GBC6198J NISSAN NV200

			Estimated	
No	Qty	Parts Description	Parts Price	
<u>Special Nett Items</u>				
1	10	Rear bumper clips	\$	80.00
2	6	Rear end lower panel top garnish clips	\$	50.00
3	1	Rear end lower panel sealant	\$	120.00
4	8	Rear tailgate inner trim board clips	\$	50.00
5	6	Rear tailgate outer garnish clips	\$	50.00
6	1	Rear floor panel sealant	\$	120.00
7	1	Rear windscreen glass sealant	\$	80.00
8	3	Rear windscreen mounding	\$	320.00
9	2	Rear bumper reverse sensor	\$ 200	250.00
10	1	Rear no plate with garnish	\$	80.00
11	2	Rervese sensor	\$	500.00
Sub-total special nett			\$	1,700.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

GB6198L NISSAN NV350 200

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts, main body frame RR frame damaged	\$ 1,500.00	500
2	To putty and spray painting rear portion, boot inside out, bumper, right fender dent, main frame metal, rear end panel, gutter side panel for left and right	\$ 1,500.00	600
3	To check rear lighting and wiring.	\$ 60.00	30
4	To remove and install rear tailgate lock mechanism.	\$ 80.00	50
5	To remove & install rear windscreen glass to facilitate the repair.	\$ 150.00	80
6	To apply anti rust proofing to rear affected area including behind spare tyre area	\$ 250.00	50
7	To remove and install rear bumper reverse sensor.	\$ 80.00	30
8	To remove and install rear exhaust muffler assy.	\$ 250.00	X
9	To remove and rear internal internal trims to facilitate the repair	\$ 80.00	30
10	To remove and install rear camera to facilitate the repair	\$ 80.00	X
Total labour :		\$ 4,030.00	

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: