

**AUTOWERKS****ZOOM AUTOWERKS PTE LTD**130 Bedok Reservoir Road
#08-1339 Singapore 470130

Tel: 9450 7920

* zoomautowerks@gmail.com

7 June 2022

REG NO. : SKJ 6912 X
MAKE/MODEL : VOLKSWAGEN GOLF**ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE**

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding <i>11</i>	\$ 85.00 X
1	Rear tailgate <i>R</i>	\$ 1,393.00 X
2	Rear tailgate dampers <i>11</i>	\$ 243.20 X
2	Rear tailgate lamps <i>11</i>	\$ 730.00 X
1	Rear tailgate lock <i>11</i>	\$ 280.60 X
1	Rear tailgate logo <i>11</i>	\$ 440.00 X
1	Rear tailgate weatherstrip <i>11</i>	\$ 215.00 X
1	Rear tailgate "GOLF" emblem <i>dec</i>	\$ 68.50 ✓
2	Rear taillamps <i>11</i>	\$ 778.00 X
1	Rear end panel <i>R</i>	\$ 485.00 X
1	Rear end panel inner garnish <i>11</i>	\$ 185.00 X
1	Rear bumper <i>DD / Re</i>	\$ 1,289.00 ✓
2	Rear bumper side brackets <i>11</i>	\$ 76.00 X
1	Rear bumper inner garnish <i>one</i>	\$ 125.00 ✓
1	Rear bumper diffuser <i>grab</i>	\$ 375.00 ✓
2	Rear bumper reflectors <i>na</i>	\$ 137.00 X
1	Rear bumper reinforcement <i>buf</i>	\$ 485.00 ✓
2	Rear bumper side retainers <i>11</i>	\$ 137.00 X
1	Rear bumper tow hook cover <i>11</i>	\$ 18.20 X
1	Rear exhaust silencer <i>11</i>	\$ 893.00 X
2	Rear exhaust mountings <i>11</i>	\$ 85.00 X
2	Rear number plate lamps <i>one</i>	\$ 131.00 ✓
		\$ 8,654.50
Less 10%		\$ 865.45
		\$ 7,789.05

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$	11	80.00	X
1	Rear bumper clip (1 set)	\$	1.11	55.00	40
1	Rear sticker (1 set)	\$	1.11	1,000.00	850
1	Rear number plate with holder	\$	one	100.00	50
1	Rear reverse sensor (1 set)	\$	one	350.00	X
		\$		1,585.00	

S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$		80.00	20
2	To remove and refit inner garnishes.	\$		150.00	80
3	To remove and refit rear reverse sensor.	\$		150.00	40
4	To transfer rear tailgate mechanism and wiring assembly.	\$	11	80.00	X
5	To remove and refit rear windscreen glass.	\$	11	180.00	X
6	To remove, refit and replace exhaust silencer and mountings.	\$	11	150.00	X
7	To apply undercoating.	\$	11	150.00	X
8	Panel beating.	\$		1,500.00	400
9	To re-spray painting on the affected areas.	\$		1,400.00	600
		\$		3,840.00	

GRAND TOTAL :

\$ 13,214.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2413.50
102
P-2172.15
S-N-940
L-1140
4252.15
202
3401