

Boost Automotive Pte Ltd

6 Yishun Industrial Street 1 #05-20 North View Bizhub Singapore 768090

HP: 9362 8159 Email: boostautomotive.sg@gmail.com ROC: 202144603K

June 1, 2022

Reg No.: FBL 1037 B

Model: Suzuki Burgman UH200

SUPPLEMENTARY ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

S/N	DESCRIPTION	QTY	UNIT PRICE S\$	AMT S\$	
<u>List Items</u>					
1	Lever, Front Brake	1	70.62	70.62	
2	Balancer	1	31.14	31.14	
3	Shield, Leg Front (Black)	1	436.77	436.77	
4	Shield, Leg Lower (Grey)	1	277.99	277.99	
5	Shield, Leg Lower Rear (Black)	1	244.60	244.60	
6	Shield, Leg Side Right (Black)	1	254.55	254.55	
7	Footboard, Right (Black)	1	54.25	54.25	
8	Cover, Frame Right (Black)	1	312.98	312.98	
9	Handle, Pillion Rider Right (Black)	1	299.17	299.17	
10	Cover, Muffler	1	136.10	136.10	
11	Cushion	2	16.69	33.38	
12	Cover, Muffler RR	1	79.93	79.93	
13	Stay, Rear Cover	1	69.34	69.34	
14	Cushion	3	14.45	43.34	
15	Cushion	3	15.73	47.19	
16	Body, Muffler, UH200AL6	1	2,809.61	2,809.61	
17	Connector, Muffler	1	45.90	45.90	
				5,246.86	
				Less 10%	524.69
				Sub-total	4,722.17
S/N	<u>Labour Charges</u>				
1	5 Hours	5	90.00	450.00	
				Sub-total	450.00
				Grand Total	5,172.17