

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT122005339/49x3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBL1037B

at Workshop m/s

of

300 St Andrews
9 Kakeri, Kakeri Road / 01-01

Insured:

SYH 84631

Policy No.

Claims No.

SNM 2203775/002


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$7k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4
20

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Ruger 93628159

Vehicle: IN / OUT

Date:

Person Contacted:

7706

Veh No: FBL1037B

Yr Regn:

13/06/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Burgmen 200 ABS

Make:

Suzuki UH200A

c.c

200

Colour:

Any

A/C: Insured / Std / NI / NA

Sp. Reading

31890

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MLCC9112/90402408

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110/90-13

R:

130/70-12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

metzeler

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

28/05/22

D.O.I.

7/6/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 82529

have wry sticker 27/1/20

more 8 4471

27/6/22 4/5 \$ 2400 informed Ruger (Red \$ 3532.93, 606/)

Date/Time, File Pass to?



: Preli. Report

1) 28/6/22 Ruger



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

3

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

MER-TP

Lump Sum / I.B.A. (\$

2400

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Boost Automotive Pte Ltd

6 Yishun Industrial Street 1 #05-20 North View Bizhub Singapore 768090

HP: 9362 8159 Email: boostautomotive.sg@gmail.com ROC: 202144603K

Reg No.: FBL 1037 B
Model: Suzuki Burgman UH200

June 1, 2022

Not Authorised
2/s 2400
4 days
7/6/22 Zhephwa After rep
HP 900966 of

SUPPLEMENTARY ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

S/N	DESCRIPTION	QTY	UNIT PRICE S\$	AMT S\$
<u>List Items</u>				
<i>lever</i> 1	<i>Lever</i> , Front Brake <i>o/s</i>	<i>CU7</i> 1	70.62	70.62 ✓
2	Balancer <i>o/s</i>	<i>CU7</i> 1	31.14	31.14 ✓
3	Shield, Leg Front (Black) <i>o/s</i>	<i>CU7</i> 1	436.77	436.77 ✓
4	Shield, Leg Lower (Grey) <i>o/s</i>	<i>CU7</i> 1	277.99	277.99 ✓
5	Shield, Leg Lower Rear (Black) <i>o/s</i>	<i>CU7</i> 1	244.60	244.60 ✓
6	Shield, Leg Side Right (Black) <i>o/s</i>	<i>CU7</i> 1	254.55	254.55 ✓
7	Footboard, Right (Black) <i>o/s</i>	<i>CU7</i> 1	54.25	54.25 ✓
8	Cover, Frame Right (Black) <i>o/s</i>	<i>CU7</i> 1	312.98	312.98 ✓
9	Handle, Pillion Rider Right (Black) <i>o/s</i>	<i>CU7</i> 1	299.17	299.17 ✓
10	Cover, Muffler	<i>CU7</i> 1	136.10	136.10 ✓
11	Cushion <i>muffler</i>	<i>Rec</i> 2	16.69	33.38 ✓
12	Cover, Muffler RR	<i>o/s</i> 1	79.93	79.93 ✓
13	Stay, Rear Cover	<i>Surf</i> 1	69.34	69.34 ✓
14	Cushion <i>stopper</i>	<i>rec</i> 3	14.45	43.34 ✓
15	Cushion <i>washer</i>	<i>rec</i> 3	15.73	47.19 ✓
16	Body, Muffler, UH200AL6	<i>R</i> 1	2,809.61	2,809.61 X
17	Connector, Muffler	<i>rec</i> 1	45.90	45.90 ✓
				5,246.86
Less 10%				524.69
Sub-total				4,722.17

S/N Labour Charges

1	5 Hours	5	90.00	450.00 <i>420</i>
Sub-total			450.00	

S/N Loss of Use

1	5 Working Days	5	50.00	250.00
Sub-total			250.00	
Grand Total			5,422.17	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2437.25
480
2817.25
102
2625.52
420
7245.52

Boost Automotive Pte Ltd

6 Yishun Industrial Street 1 #05-20 North View Bizhub Singapore 768090

HP: 9362 8159 Email: boostautomotive.sg@gmail.com ROC: 202144603K

June 9, 2022

Reg No.: FBL 1037 B

Model: Suzuki Burgman UH200

SUPPLEMENTARY ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

<u>S/N</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE S\$</u>	<u>AMT S\$</u>
<u>List Items</u>				
1	Printing of Camo Stickers	nec 4	139.10	556.40
				556.40
			Less 10%	55.64
			Sub-total	500.76
<u>Labour Charges</u>				
1	Removal of current stickers sticky gum	1	100.00	100.00
2	Installation of new stickers	1	160.00	160.00
			Sub-total	260.00
			Grand Total	760.76

5932 93