

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9872A*Not Authorized
Pharmacy Bypass***AAD2206-****03067-93**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

07 JUN 2022**SHD9872A**

JTDKB3FU803092715

200303878K

TOYOTA

PRIUS GEN 4

06/06/2022

YN1470A/ EQ

13/11/2020

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 PANEL SUB-ASSY, QUARTER, RH
- 1 LINER, REAR WHEEL HOUSE, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH
- 1 LAMP ASSY, REAR, RH
- 1 SPOILER SUB-ASSY, REAR
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 BOARD ASSY, BACK DOOR TRIM
- 1 WEATHERSTRIP, BACK DOOR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH

LIST

\$	<i>Av/1w</i>	485.60	✓
\$	<i>R</i>	332.70	X
\$	<i>Pr</i>	22.00	✓
\$	<i>Pr</i>	374.50	X
\$	<i>R</i>	132.60	X
\$	<i>Dis</i>	132.60	✓
\$	<i>Pr</i>	39.00	X
\$	<i>R</i>	871.50	✓
\$	<i>Pr</i>	139.80	X
\$	<i>CM</i>	339.60	✓
\$	<i>CM</i>	261.00	✓
\$	<i>CM</i>	293.60	✓
\$	<i>Pr</i>	1,575.40	X
\$	<i>R</i>	1,147.80	X
\$	<i>na</i>	54.60	} X
\$	<i>na</i>	54.60	
\$	<i>na</i>	47.90	
\$	<i>Pr</i>	913.60	
\$	<i>Pr</i>	259.20	
\$	<i>Pr</i>	372.30	
\$	<i>Pr</i>	126.70	
\$	<i>R</i>	651.00	
\$	<i>Pr</i>	242.50	
\$	<i>Pr</i>	242.50	
\$	<i>R</i>	61.00	
\$	<i>R</i>	61.00	

TOTAL \$ 9,234.60

Trans-cab Auto Services Pte Ltd**AAD2206-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9872A

25%	\$	2,308.65
	\$	<u>6,925.95</u>

Special Nett

1SET PARKING AID	\$	Pr	700.00	X
1SET REAR BUMPER CLIP	\$	na	95.00	6000
1 REAR SPOILER CLIP	\$	na	65.00	} X
1 FENDER LINER CLIP	\$	na	65.00	
2 WINDSCREEN SEALANT	\$	na	150.00	
1 WINDSCREEN MOULDING	\$	na	200.00	
1 WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	
1 REAR TAILGATE STICKER "Trans-Cab"	\$	na	80.00	
1 REAR TAILGATE STICKER "6555-3333"	\$	na	80.00	
1 REAR BUMPER PROTECTOR	\$	na	180.00	
1SET REAR BUMPER RETAINER CLIP	\$	na	85.00	
1 END PANEL TRIM CLIP	\$	na	65.00	
TOTAL	\$		1,895.00	

TOTAL PARTS	\$	8,820.95
--------------------	-----------	-----------------

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ na 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 Pr

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 6000

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ na 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ na 180.00 X

Trans-cab Auto Services Pte Ltd**AAD2206-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9872A

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ *nn* 480.00 X

To transfer of Fender fittings, attachments and perform water seepage test.

\$ 4 480.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 4 380.00 X

To check steering geometry and computer wheel alignment

\$ 4 220.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 *301*

Towing Fees

\$ 4 150.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 *4401*

To reinstall rear bumper parking sensor.

\$ 170.00 *501*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ 4 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ 4 220.00 X

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.

\$ 4 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ 4 380.00 X

TOTAL \$ 9,300.00**Over All Total \$ 18,120.95**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days**25 DAYS***5 days*