

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



21/6 survey 290

Steve (LKK)

21/6/22, 11.00am

m n

3 d p

PIP

1/2 R L

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 62014
Date Estimated : 01/06/2022
Prepared By : Yap Mee Key

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Lee Lui Shiong (Li Ruixiong)
28 UPPER BUKIT TIMAH VIEW

SINGAPORE 588151

- ACCOUNT - 224093
Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNF308R	WB42DU030S391502	12/05/2022	IX3	18

DESCRIPTION

To replace rear bumper.

850 / 1,275.00

To respray rear bumper.

986 / 1,038.00

To check electrical wiring system.

168 / 177.00

To remove old PDC assembly, re place damaged parts and reconnect to new bumper including re connect to new bumper and conduct check for proper function.

X 168 / 177.00

Sundries

80.00

Total Labour 1: 2,747.00

DESCRIPTION

PLASTIC NUT FOR COARSE THREADED PIN

QTY PRIC VALUE

EXPANDING NUT L=19.9MM

10 0.85 8.50

C CLIP FOR PLASTIC NUT

10 1.40 14.00

PLASTIC NUT

10 1.10 11.00

EXPANDING RIVET

7 2.75 19.25

REAR BUMPER PANEL PRIMED (PDC+PMA)

15 0.50 7.50

REAR BUMPER BOTTOM TRIM PANEL (GLOS

1 1,593.30 1,593.30

REAR BUMPER COVER PAINTED (FROZEN G

1 297.75 297.75

ADAPTER FOR SUPPORT REAR

1 274.35 274.35

Undershield,

1 166.90 166.90

Torsion stru

1 102.20 102.20

Torsion stru

1 43.05 43.05

PLUG BLACK D=5MM

1 48.25 48.25

Control unit

6 0.95 5.70

SENSOR LEAD SMART OPENER TOP

1 514.25 514.25

SENSOR LEAD SMART OPENER BOTTOM

1 51.95 51.95

1 51.95 51.95

Total Parts : 3,209.90

6073.10